Date Received 11-20 73

MECK COUNTY HEALTH DEPT.
RECEIVED
NOV 26 1973

APT No. 7251

T. C. No. 031-051-33

Map Date

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER HARDY (LAST) TROY (FIRST) D. (MIDDLE)

2) ADDRESS OF OWNER Route 5, Pine Island Drive, Charlotte, N.C. ZIP 28206

3) PHONE NO. Home 399-5735 Office


4) LOCATION OF PROPERTY Stoney Ridge Drive (STREET OR COUNTY ROAD)

5) SUBDIVISION Pine Island Country Club LOT NO. 11 BLOCK NO. 1

MAP BOOK NO. 12 PAGE NO. 362

6) DEED REFERENCE: DEED BOOK 3575 PAGE NO. 575

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge.



104.9' to Mt. Holly Land Rd. 127, West

7) ACCURATELY DIAGRAM & DIMENSION LOT

Troy D Hardy
OWNER

FORM NO. E-1-9-1-72

HEALTH DEPARTMENT'S COPY

MECKLENBURG COUNTY HEALTH DEPARTMENT
INTER-OFFICE COMMUNICATION

DATE: April 24, 1974

TO: Luther Bridgeman
Environmentalist

FROM: W. Everette Lynn, Jr. WEL
Soil Scientist

SUBJECT: Apt. 7251 (T. B. Harkey)
Lot No. 11, Block 1, Stoney Ridge Drive
Pine Island Country Club
4-19-74

The lot consists of soils of the Enon series. These soils have plastic and sticky clay subsoils which contain swelling clay minerals. These soil characteristics result in inadequately slow permeability and percolation rate.

Based on this investigation, the lot appears unsuitable for installation of a septic tank system.

MECKLENBURG COUNTY
Department of Public Health
1200 Blythe Boulevard
Charlotte, North Carolina 28203

Telephone 374-2113

Date Issued
1. 3-11-74
2. 4-25-74
3. _____

SITE DISAPPROVAL REPORT
INDIVIDUAL SEPTIC TANK SYSTEM WITH SUBSURFACE, SOIL ABSORPTION, EFFLUENT DISCHARGE

SDR No. [illegible]
T.C. No. [illegible]-051-33

NAME OF OWNER Hanley, Troy T.

ADDRESS OF OWNER [illegible], Plum Island Drive ZIP 2209

LOCATION OF LOT [illegible], Lot 11-1

The lot described above has been disapproved for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge due to the following:

FAILURE TO PASS PERCOLATION TEST (60 minutes per inch or less)

	Test No.	Date of Test	Percolation Rate
X	1.	[illegible]	[illegible] min/in
____	2.	_____	_____ min/in
____	3.	_____	_____ min/in

X ON SITE INSPECTION REVEALED LOT TO BE UNSUITABLE FOR THE FOLLOWING REASON(S) 4-19-74 - The lot consists of soils of the Iron series. These soils have plastic and sticky clay subsoils which contain swelling clay minerals. These soils characteristics result in inadequately slow permeability and percolation rate.

W. Everette Cannaday Jr.
Soil Scientist

[illegible]
Environmentalist

(Stencil No.)
KMD 398
8/70

FORM NO.
E-19-8-14-70