

6008 CORKSTONE DR

13524231

7/22/08

marliwr

Groundwater and Wastewater Services File Imaging Project
May 2007
Barcode Font = IDAutomationHC39M

MECKLENBURG COUNTY · ENVIRONMENTAL HEALTH ·


[redacted] **PLOT PLAN**

1200 BLYTHE BOULEVARD
CHARLOTTE, NC 28203
PHONE (704) 376-4603

FILE: 15662

TC: 135-242-30

Draw in and name all roads adjoining the property. Draw in and accurately dimension the lot concerned. Accurately indicate property boundaries, proposed and/or existing structures and driveways, underground utilities, and wells and springs within 100 feet of the proposed building or drainfield.



ORIGINAL INSTALLATION

2 - Bed
1.5' x 45' x 12"

1500 ST + 1000 LT

COMM. WATER SYSTEM

Signed: [signature]

Date: 3-5-87

File #15662

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
On Premises Waste Disposal Section

105128

Field I.D. Number _____ Phone:

Site Sampled SURFACE Home _____

Address 6008 CORKSTONE Work _____ Lab I.D. # 4701

Source Sampled SURFACE Delivered To Lab On: Rec'd By [illegible]

Sample & Evaluation By [illegible] Date 3-24 Time 4 ☐AM ☐PM MAR 23 1987 Data Rec'd _____

Date Sampled 3-24 Time 1030 ☐AM ☐PM Delivered By [illegible] Time 1615

Chloride ☐ _____ppm	Total Coliform ☐ _____/100 ml	Cu ☐ _____ppm	Ca ☐ _____ppm
Nitrate ☐	Non-Coliform ☐ _____/100 ml	Fe ☐ _____ppm	Mg ☐ _____ppm
UV spec _____ppm	Fecal Coliform ☑ 0 /100 ml	Mn ☐ _____ppm	Hardness ☐ _____ppm
Chromatrophic acid _____ppm	Fecal Strep ☑ 0 /100 ml	Zn ☐ _____ppm	pH ☐ _____Units

Remarks _____

MAR 26 1987

Date Completed _____ Lab Director James F. Ware
LABORATORY DIRECTOR

(1) Well greater than 50' from building foundation?	☑ Y	☐ N	☐ UNK*	COMMENTS:
(2) Well greater than 50' from other source of pollution?	☐ Y	☐ N	☐ UNK*	
(3) Site sloped to divert surface water?	☐ Y	☐ N	☐ UNK*	
(4) Well house provided?	☐ Y	☐ N	☐ UNK*	
(5) Enclosure properly drained and free of storage?	☐ Y	☐ N	☐ UNK*	
(6) Well grouted to depth of 20'?	☐ Y	☐ N	☐ UNK*	
(7) Well properly vented?	☐ Y	☐ N	☐ UNK/NA*	
(8) Slab extending at least 2' from casing provided?	☐ Y	☐ N	☐ UNK*	
(9) Casing extended at least 6" above slab?	☐ Y	☐ N	☐ UNK*	
(10) Sanitary seal intact?	☐ Y	☐ N	☐ UNK/NA*	
(11) Septic tank effluent absent on surface of ground?	☐ Y	☐ N	☐ NR/NA*	

*SPECIFY IN COMMENT SECTION.

!naa! _____ !salutation! _____

PARAGRAPHS

_____ _____ _____ _____ _____

_____ _____ _____ _____ _____

Notified _____

File # 15662

Carkston

MECKLENBURG COUNTY

Office of the County Attorney

M E M O R A N D U M

TO: John Barry, Director, Environmental Health

FROM: Sandra T. Bisanar, Associate County Attorney Sandra T. Bisanar

DATE: March 20, 1987

RE: Septic System Complaint from Louis Andre

Pursuant to our earlier telephone conversation, attached is a copy of a letter I received from a man by the name of Louis Andre concerning a septic tank complaint in the Farmwood Subdivision. Since this letter was addressed to the attention of the Director of the Department of Environmental Health, I assume that your office received a copy. I would appreciate it if you would check into this matter, and if I can be of assistance please let me know.

Enclosure

STB/jrw

MECK COUNTY DEPARTMENT OF
RECEIVED
MAR 23 1987
ENVIRONMENTAL HEALTH

720 East Fourth Street • P.O. Box 31787 • Charlotte, North Carolina 28231 • (704) 336-2472

March 1, 1987
6008 Corkstone Dr.
Charlotte, NC 28212

Mecklenburg County
Department of Environmental Health
1200 Blythe Blvd.
Charlotte, NC

Attention: Director

Dear Sir:

The purpose of this letter is to call your attention to an unsafe and hazardous health condition which currently exists at my property.

Untreated sewage from my neighbors septic system has been flowing onto my property and into a public drainage ditch creating a health hazard.

The properties are identified as Lot 41S (mine) and 40S (my neighbors) of FARMWOOD, Section #15, Map 1 as shown in Map Book 18 at page 9 of the Mecklenburg county, NC Public Registry.

My family and I have resided at this location since August 1985 and had hoped that this condition would be corrected. The condition is a year round problem but has been exacerbated by the recent rainfall.

I am a Registered Professional Civil Engineer in North Carolina and feel certain the county has errored in issuing a building permit for my neighbor's home. The soil conditions which prevail in the vicinity of the two lots are not pervious enough to allow for the proper drainage required for a septic system which has been constructed.

Please initiate an investigation of this hazardous condition in order to insure corrective action is taken to prevent the spread of any disease.

It is with this letter that I serve notice to the County concerning its liabilities in connection with this health hazard.

Sincerely,

L Andre

Louis Andre


cc: County Attorney

APT. NO. 15662 YEAR 1985

TAX NO. 135=252=30

ST. ADDRESS 6016 Corkstone Dr.

2 of 2



MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

Others
Evanston, Ill. U. S. Pat. Nos. 3,147,561; 3,220,133 U. K. Pat. No 935,479 Pending
1265R

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
RECORDAX® APERTURE CARD MANUFACTURED IN THE U.S.A. FOR EASTMAN KODAK COMPANY