B

Date Received 7-14-73
7-13-73

MECK COUNTY HEALTH DEPT.
RECEIVED
JUL 16 1973

APT No. 6664

T C. No.

Map Date

MECKLENBURG COUNTY HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER Busby (LAST) Guccaro (FIRST) Taylor (MIDDLE)

2) ADDRESS OF OWNER 3001 Wamath Drive, Charlotte ZIP 28210

3) PHONE NO Home 364-3775 Office 827-4351 Ex. 423


4) LOCATION OF PROPERTY Lot 22 South Ford Road (STREET OR COUNTY ROAD)

5) SUBDIVISION Pine Island Country Club LOT NO 22 BLOCK NO. 5

MAP BOOK NO 14 PAGE NO 267

6) DEED REFERENCE DEED BOOK 3021 PAGE NO. 453

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

W. T. Busby, Jr.
OWNER

FORM NO E-1-9-1-72

HEALTH DEPARTMENT'S COPY

MECKLENBURG COUNTY
Department of Public Health

1200 Blythe Boulevard
Charlotte, North Carolina 28203
Telephone 374-2113

Date Issued
1. [illegible] 1973
2. _____
3. _____

SDR No. _____
T.C. No. _____

SITE DISAPPROVAL REPORT
INDIVIDUAL SEPTIC TANK SYSTEM WITH SUBSURFACE, SOIL ABSORPTION, EFFLUENT DISCHARGE

NAME OF OWNER _____

ADDRESS OF OWNER _____ ZIP [illegible]10

LOCATION OF LOT [illegible], Pine Island Country Club

The lot described above has been disapproved for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge due to the following:

FAILURE TO PASS PERCOLATION TEST (60 minutes per inch or less)

	Test No.	Date of Test	Percolation Rate
[illegible]	1.	7- [illegible]	[illegible] min/in
____	2.	_____	_____ min/in
____	3.	_____	_____ min/in

[illegible] **ON SITE INSPECTION REVEALED LOT TO BE UNSUITABLE FOR THE FOLLOWING REASON(S)** (8-1-73) Soils are of the Mecklenburg and [illegible] series. These soils have plastic clay subsoils which contain swelling clay minerals. In addition, the Helena soils have a perched high water table during periods of high rainfall. These factors result in inadequately slow percolation rate and permeability.

_____ Soil Scientist

_____ Environmentalist

(Stencil No.)
HHD 398
8/70

FORM NO.
E-19-8-14-70