R Date Received 2-3-94 APT No. 7456

T. C. No.

Map Date

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER Burgess (LAST) Larry (FIRST) (MIDDLE)

2) ADDRESS OF OWNER 308 Archchead Dr Apt 6 ZIP 28213

3) PHONE NO. Home 596 4683 Office 374 - 4324


4) LOCATION OF PROPERTY Whispering Oaks Drive (STREET OR COUNTY ROAD)

5) SUBDIVISION Whispering Oaks LOT NO. BLOCK NO.

MAP BOOK NO PAGE NO.

6) DEED REFERENCE DEED BOOK PAGE NO.

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

Larry Burgess
OWNER

FORM NO. E-1-11-1-70

HEALTH DEPARTMENT'S COPY

MECKLENBURG COUNTY
Department of Public Health
1200 Blythe Boulevard
Charlotte, North Carolina 28203

Telephone 374-2113

Date Issued
1. 2-15-74
2. 2-25-74
3. 3-5-74

SDR No. 7486
T.C. No. 105-161-18
12-14-73

SITE DISAPPROVAL REPORT
INDIVIDUAL SEPTIC TANK SYSTEM WITH SUBSURFACE, SOIL ABSORPTION, EFFLUENT DISCHARGE

NAME OF OWNER Burgess, Larry

ADDRESS OF OWNER [illegible] Apt. #5 ZIP 28213

LOCATION OF LOT Whispering Oaks Drive

The lot described above has been disapproved for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge due to the following:

FAILURE TO PASS PERCOLATION TEST (60 minutes per inch or less)

	Test No.	Date of Test	Percolation Rate
X	1.	2-15-74	[illegible] min/in
X	2.	2-20-74	160 min/in
X	3.	2-27-74	160 min/in

____ **ON SITE INSPECTION REVEALED LOT TO BE UNSUITABLE FOR THE FOLLOWING REASON(S)** 2-28-74 - Soils were found to be of the [illegible] series. These soils have plastic and sticky clay subsoils which contain swelling clay minerals. They may also have a perched high water table during periods of high rainfall. These soil characteristics result in inadequately slow percolation rate and poor stability.

W. Everette Lyons Jr. / John R. Atkinson
Soil Scientist / Environmentalist

(Stencil No.)
EHD 398
8/70

FORM NO.
E-19-8-14-70

MECKLENBURG COUNTY HEALTH DEPARTMENT
INTER-OFFICE COMMUNICATION

DATE: March 4, 1974

TO: RR
Randy Reynolds
Environemntalist

FROM: W. Everette Lynn, Jr. WEL
Soil Scientist

SUBJECT: APT #7486 (L. Burgess)
Whispering Oaks Drive
Whispering Oaks Subdivision
2-28-74

Soils were found to be of the Helena series. These soils have plastic and sticky clay subsoils which contain swelling clay minerals. They may also have a perched high water table during periods of high rainfall. These soil characteristics result in inadequately slow percolation rate and permeability.

Based on this investigation, the lot appears unsuitable for installation of a septic tank system.

WEL:jdg