Date Received 4-9-73

APT No. 5142

T. C No.

Map Date

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER ESTATE OF LOIS D. PORTER (LAST) - FIRST UNION NATIONAL BANK AND ALPHEUS A. (FIRST) PORTER, CO-EXECUTORS (MIDDLE)

2) ADDRESS OF OWNER Trust Department, First Union National Bank ZIP 28285
Charlotte, North Carolina

3) PHONE NO. Home None Office Leonard Richardson - 374-6424
(Trust Dept., FUNB)

4) LOCATION OF PROPERTY On Delshire Lane, Mecklenburg County, North Carolina
(STREET OR COUNTY ROAD)


5) SUBDIVISION Sandy Porter Property LOT NO. 5 BLOCK NO. C

MAP BOOK NO. 14 PAGE NO. 523

6) DEED REFERENCE DEED BOOK 1312 PAGE NO. 273

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge

SEE ATTACHED XEROX COPY OF SUBDIVISION PLAT.



7) ACCURATELY DIAGRAM & DIMENSION LOT

FIRST UNION NATIONAL BANK, CO-EXECUTOR OF
ESTATE OF LOIS D. PORTER
BY: OWNER

(CORPORATE SEAL)

FORM NO E-1-9-1-72

HEALTH DEPARTMENT'S COPY

MECKLENBURG COUNTY
Department of Public Health
1200 Blythe Boulevard
Charlotte, North Carolina 28203

Telephone 374-2113

Date Issued
1. April 26, 1973
2. _____
3. _____

SDR No. 5 47
T.C. No. _____

SITE DISAPPROVAL REPORT
INDIVIDUAL SEPTIC TANK SYSTEM WITH SUBSURFACE, SOIL ABSORPTION, EFFLUENT DISCHARGE

NAME OF OWNER _____

ADDRESS OF OWNER c/o [illegible] 3220 Reece Rd. ZIP [illegible]209

LOCATION OF LOT _____

The lot described above has been disapproved for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge due to the following:

FAILURE TO PASS PERCOLATION TEST (60 minutes per inch or less)

	Test No.	Date of Test	Percolation Rate
X	1.	[illegible]	30+ min/in
____	2.	_____	_____ min/in
____	3.	_____	_____ min/in

____ ON SITE INSPECTION REVEALED LOT TO BE UNSUITABLE FOR THE FOLLOWING REASON(S) _____

_____

_____

_____

[signature]
Environmentalist

(Stencil No.)
EHD 398

FORM NO.
E-19-8-14-70