Date Received 5/24/77

APT No 12486

T C No 033.0757

Map Date 4-19-77

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER GRIFFIN (LAST) JOHN (FIRST) L (MIDDLE)

2) ADDRESS OF OWNER RT. 9 BOX 217E ZIP 28208

3) PHONE NO Home 399-3948 Office


4) LOCATION OF PROPERTY PARGO RD (STREET OR COUNTY ROAD)

5) SUBDIVISION OAKDALE ACRES LOT NO 15 BLOCK NO E

MAP BOOK NO 6 PAGE NO 273

6) DEED REFERENCE DEED BOOK 2584 PAGE NO 401

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

SIMPSON RD.

OWNER John L Griffin

FORM NO E-1-8-1-72

HEALTH DEPARTMENT'S COPY

SOIL INVESTIGATION REPORT

Date of Investigation May 31, 1977 APT NO. 12 486

Owner John L. Griffin T.C. 033-025-17

Location of Property Page Rd Lot # 15

Soil Suitability Ratings

Soil Properties	Soil 1	Soil 2	Soil 3	Soil 4
1. Soil Series	Exum-Wilkes	Helena		
2. Soil Slope	Suitable 2-6%	Suitable 2-7%		
3. Soil Depth	Unsuitable 40"	Suitable 48"		
4. Soil Texture	unsuitable 2:1 Expanding Clay	unsuitable 2:1 Expanding Clay		
5. Soil Structure	unsuitable Mass [illegible]	unsuitable Mass [illegible]		
6. Restrictive Horizons	-			
7. Soil Drainage	suitable [illegible] water table	unsuitable perched high water Table		
8. Soil Permeability (Percolation Rate)	unsuitable [illegible] slow	unsuitable >200 min/in		
9. Other				
10. Overall Rating	unsuitable	unsuitable		


Remarks:
Recommendations Based on this investigation, the soils on the site are considered to be unsuitable for the installation of septic tank systems.

[illegible]

William A. Wells
Soil Scientist

3/15/75
F.S. 559

DIAGRAM OF PROPERTY



3/18/75
EHD 539

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

DATE ISSUED
1. 6-1-77
2.
3.

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

SIR NO. 12486
T.C. NO. 033-075-17
L.P. DATE 4-19-77

NAME OF OWNER Griffin, John L.

ADDRESS OF OWNER Rt.9, Box 217E, Charlotte, NC 28208

LOCATION OF LOT Fargo Road, Lot 15, BLock E

The lot described above is not recommended for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge due to the following:

Soil Permeability Unsuitable.

Percolation rate in excess of 200 min/in.

John R. Adkisson

John R. Adkisson, Environmentalist
On Premises Waste Disposal Section

JRA: glr

(Stencil No.)
ENV 368
8/74

FORM NO.
E-11-8-21-74