Date Received 7/12/77

APT No. 12831

T. C. No. PO 135-3[illegible]

Map Date

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER BOB McLEMORE & Co, INC.
(LAST) (FIRST) (MIDDLE)

2) ADDRESS OF OWNER PO Box 25746 CHARLOTTE, N.C. ZIP 28

3) PHONE NO Home _____ Office 545-6111


4) LOCATION OF PROPERTY TIMBER RIDGE DR.
(STREET OR COUNTY ROAD)

5) SUBDIVISION FARMWOOD #6 LOT NO. 19 BLOCK NO. J

MAP BOOK NO _____ PAGE NO _____

6) DEED REFERENCE DEED BOOK _____ PAGE NO. _____

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

Peter L. Gorbel
OWNER Asst V.P.

FORM NO E1-11-3M-6-75

HEALTH DEPARTMENT'S COPY

Apt. 12831

DEPARTMENT OF HUMAN RESOURCES
DIVISION OF HEALTH SERVICES

APPENDIX H

SITE EVALUATION

(Ground Absorption Sewage Disposal)

OWNER: Bob McKenzie & Co., Inc. DATE REQUESTED: July 12, 1977

ADDRESS: P.O. Box 2546 Charlotte PLAT NO.:

COUNTY: Mec. Co. LOT SIZE: 44,000 sq. ft

LOCATION OF SITE: Timber Ridge Drive Lot No. 14 Block I Timberlake

PC 135-35 #1

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	S PS U	S PS 4-12% U	S PS U	S PS U
2. SOIL TEXTURE (12-36 in.) (Sandy, loamy, clayey, Not. .:l clay)	S PS U	S PS clay U	S PS U	S PS U
3. SOIL STRUCTURE (12-36 in.) (Clayey soils)	S PS U	S PS blocky U	S PS U	S PS U
4. SOIL DEPTH (In.)	S PS U	S PS >48" U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (In.) (Impervious Strata, rock)	S PS U	S PS U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (External & Internal)	S PS U Poorly	S PS U Poor	S PS U	S PS U
7. SOIL PERMEABILITY (Percolation Rate)	S PS U	S PS Moderate U	S PS U	S PS U
8. OTHER (Specify)	S PS U Soils	S PS U	S PS U	S PS U
9. SITE CLASSIFICATION*				
SOIL SERIES	Chewacla	Cecil		

S - Suitable PS - Provisionally Suitable U - Unsuitable


* See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slope patterns, etc.)

Recommendations/Comments: Based on this investigation the lot does not appear to have an adequate area of provisionally suitable soils for installation of a septic tank system

Described By: Ed Edmonds

Title: Soil Scientist Date: July 12, 1977

DHS Form 2601 (2/77)
Sanitation


140'
Chevalier
1
314'
330'
140'
Oac. 1
2
133'
80'
Timber Ridge Rd.

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

DATE ISSUED
1. 7-13-77
2. _____
3. _____

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

SIP NO. 12831
T.C. NO. P.O.135-351-01
MAP DATE _____

NAME OF OWNER Bob McLemore & Company, Inc.

ADDRESS OF OWNER P.O. Box 25746, Charlotte, NC 28212

LOCATION OF LOT Timber Ridge Drive, Lot 19, Block J

The lot described above is not recommended for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge due to the following:

Inadequate area of suitable soil.

Eighty percent of lot in the flood plain.

John R. Atkisson

John R. Atkisson, Environmentalist
On Premises Waste Disposal Section

JRA:glr

(Stencil No.)
ENS 339
8/74

FORM NO.
E-19-8-21-74

R