Date Received 9-10-73

APT No. 6964

T C No.

Map Date

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER Green (LAST) Donald (FIRST) P. (MIDDLE)

2) ADDRESS OF OWNER 4820 Beech Knoll C.T. ZIP

3) PHONE NO Home 536-0470 Office


4) LOCATION OF PROPERTY Windwood Circle (STREET OR COUNTY ROAD)

5) SUBDIVISION Windwood Circle. LOT NO 40 BLOCK NO.

MAP BOOK NO 1783 PAGE NO 96

6) DEED REFERENCE DEED BOOK PAGE NO

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

Donald P. Green.

OWNER Donald P.Green
By, John G.Woodruff
By request of Mr. Green.
Mr.Green purchased this lot from me Several Months ago.

FORM NO E-1-9-1-72

HEALTH DEPARTMENT'S COPY

MECKLENBURG COUNTY HEALTH DEPARTMENT

INTER-OFFICE COMMUNICATION

DATE: September 11, 1973

TO: Luther Bridgeman
Environmentalist

FROM: W. Everette Lynn, Jr. W. E. L.
Soil Scientist

SUBJECT: APT #6964 (John Woodruff)
Windwood Circle, Lot No. 40
7/25/73

Soils were found to be of the Iredell and Wilkes series. These soils have very plastic and sticky clay subsoils which contain swelling clay minerals. The Iredell soils have a perched high water table during periods of high rainfall. The Wilkes soils are shallow to impervious weathered rock material. These factors result in inadequately slow percolation rate and permeability.

Based on these observations, it is recommended that the lot be disapproved for installation of a septic tank system.

WEL:dcr

Date Received 10-2-73 APT No. 6964

MECK COUNTY HEALTH DEPT.
RECEIVED
SEP 28 1973
ENVIRONMENTAL HEALTH DIVISION

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER Green (LAST) Donald (FIRST) P (MIDDLE)

2) ADDRESS OF OWNER 4820 Beech Knoll Ct. ZIP

3) PHONE NO Home 536-0470 Office


4) LOCATION OF PROPERTY Windwood Circle (STREET OR COUNTY ROAD)

5) SUBDIVISION Windwood Circle LOT NO 40 BLOCK NO

MAP BOOK NO 1783 PAGE NO 96

6) DEED REFERENCE DEED BOOK PAGE NO

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

Donald P. Green,

OWNER Donald P. Green
By John G. Woodruff
By request of Mr. Green
Mr. Green purchased this lot from me several months ago

FORM NO E-1-9-1-72

HEALTH DEPARTMENT'S COPY

MECKLENBURG COUNTY
Department of Public Health

1200 Blythe Boulevard
Charlotte, North Carolina 28203
Telephone 374-2113

Date Issued
1. September 13, 1973
2. Oct 26, 1973
3. _____

SITE DISAPPROVAL REPORT
INDIVIDUAL SEPTIC TANK SYSTEM WITH SUBSURFACE,
SOIL ABSORPTION, EFFLUENT DISCHARGE

SDR No. 6364
T.C. No. 204-254-04

NAME OF OWNER Green, Donald P.

ADDRESS OF OWNER [illegible] Beech Knoll Court ZIP _____

LOCATION OF LOT [illegible] Road Circle, Lot 40

The lot described above has been disapproved for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge due to the following:

FAILURE TO PASS PERCOLATION TEST (60 minutes per inch or less)

	Test No.	Date of Test	Percolation Rate
A	1.	[illegible]	[illegible] min/in
X	2.	10-17-73	90* min/in
	3.		min/in

* ON SITE INSPECTION REVEALED LOT TO BE UNSUITABLE FOR THE FOLLOWING REASON(S) Soil contains swelling clay minerals and are shallow to saprolite (weathered rock material). The factors result in inadequately slow permeability and offer potential for contamination of water table.

KRD
Environmentalist

(Stencil No.)
KMD 398
8/70

FORM NO.
E-19-8-14-70