Area II

S. I. R. NO. 16064

NORTH CAROLINA
DEPARTMENT OF HUMAN RESOURCES
DIVISION OF HEALTH SERVICES
RALEIGH, NORTH CAROLINA

APPENDIX II
SITE EVALUATION

T. C. # po 193-093-25

(Ground Absorption Sewage Disposal)

OWNER: DANCY HOMES INC
ADDRESS: 1443 South Blvd
COUNTY: Mack
LOCATION OF SITE: Lot 7 off Marquet Wallace Rd

DATE REQUESTED:
PLAT NO.:
LOT SIZE: .25 A

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	S (PS) U — 2 - 10	S PS (U) — Complex	S PS U	S PS U +
2. SOIL TEXTURE (12-36 in.) (Sandy, loamy, clayey, note 2:1 Clay)	S PS (U) — 2:1 Clay	S PS (U) — 2 - 1	S PS U	S PS U
3. SOIL STRUCTURE (12-36 in.) (Clayey Soils)	S PS (U) — Massive	S PS (U) — Massive	S PS U	S PS U
4. SOIL DEPTH (In.)	S PS (U) — 48	S PS (U) — 48	S PS U	S PS U
5. RESTRICTIVE HORIZONS (In.) (Impervious Strata, Rock)	S PS (U) — Clays	S PS (U) — Clays	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (External & internal)	S PS (U) — IN Drain Way	S PS (U) — IN Drain Way	S PS U	S PS U
7. SOIL PERMEABILITY (Percolation Rate)	S (PS) U — Slow	S PS (U) — Slow	S PS U	S PS U
8. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U
9. SITE CLASSIFICATION	Unsuitable	Unsuitable		
SOIL SERIES	Helena	Helena complex slopes		

S - Suitable PS - Provisionally Suitable U - Unsuitable

* See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slope patterns, etc.


Recommendations/Comments:

Described By: W. B. Ramsey

Title: Soil Scientist Date: 8-13-79

DHS Form 2601
Sanitation
EHD 539 (3/79)

2


100
50
Serially Washed
Helena
2-10
LOT 8
LOT 7
Helena
2-10
Complex Stewes

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

S.I.R. No. 16064
T.C. No. po 193-043-25
MAP DATE
DATE 8/16/79

NAME OF OWNER Dancy Homes, Inc.

ADDRESS OF OWNER 1443 South Boulevard, Charlotte, NC 28203

LOCATION OF LOT ~~off Hoopcrest Wallace Road~~ Dancy Dr. LOT F-7 BLK.

As determined under the Rules and Regulations promulgated by the Commission for Health Services, Division of Health Services, North Carolina Department of Human Resources, Raleigh, North Carolina, the soils on the lot described above were found to be unsuitable for the installation of an individual septic tank - soil absorption system due to the following reasons:

Soil Structure Massive
Soil Permeability Unsuitable

John R. Adkisson

John R. Adkisson, Environmentalist

2