6

Date Received 8-6-73

MECK COUNTY HEALTH DEPT.
RECEIVED
AUG - 6 1973
ENVIRONMENTAL HEALTH DIVISION

APT No 6791

T C No

Map Date

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER GRAY (LAST) WILLIAM R. (FIRST) (MIDDLE)

2) ADDRESS OF OWNER 118 Brooklain Drive, Charlotte, N. C. ZIP 28214

3) PHONE NO Home 392-5797 Office


4) LOCATION OF PROPERTY Gumbranch Road, State Road 1775 (STREET OR COUNTY ROAD)

5) SUBDIVISION N/A LOT NO N/A BLOCK NO N/A

MAP BOOK NO N/A PAGE NO N/A

6) DEED REFERENCE DEED BOOK 3213 PAGE NO 174

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

William R Gray
OWNER

FORM NO E-1-9-1-72

HEALTH DEPARTMENT'S COPY

MECKLENBURG COUNTY HEALTH DEPARTMENT
INTER-OFFICE COMMUNICATION

DATE: August 10, 1973

TO: Luther Bridgeman
Environmentalist

FROM: W. Everette Lynn, Jr. W.E.L.
Soil Scientist

SUBJECT: Corner Gumbranch Road and State Road 1775
APT #6791 (Gray)

8-10-73 Soils were found to be of the Enon and Mecklenburg series. These soils have very plastic clay subsoils which contain swelling clay minerals. This results in inadequately slow perc. and permeability. Based on these observations, disapproval is recommended.

MECKLENBURG COUNTY
Department of Public Health
1200 Blythe Boulevard
Charlotte, North Carolina 28203

Telephone 374-2113

Date Issued
1. August 30, 1973
2. _____
3. _____

SDR No. 8791
T.C. No. _____

SITE DISAPPROVAL REPORT
INDIVIDUAL SEPTIC TANK SYSTEM WITH SUBSURFACE, SOIL ABSORPTION, EFFLUENT DISCHARGE

NAME OF OWNER [illegible]

ADDRESS OF OWNER 116 [illegible] ZIP 28214

LOCATION OF LOT [illegible]

The lot described above has been disapproved for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge due to the following:

FAILURE TO PASS PERCOLATION TEST (60 minutes per inch or less)

	Test No.	Date of Test	Percolation Rate
X	1.	8-3 [illegible]	[illegible] min/in
____	2.	_____	_____ min/in
____	3.	_____	_____ min/in

X **ON SITE INSPECTION REVEALED LOT TO BE UNSUITABLE FOR THE FOLLOWING REASON(S)** Soils are of the Enon and [illegible] series.

[illegible] soils have very plastic clay subsoils which contain [illegible] clay minerals. This results in inadequately slow percolation rate and permeability.

W. Scott Lyons, Jr.
Soil Scientist

Environmentalist

(Stencil No.)
HMD 398
8/70

FORM NO.
E-19-8-14-70