

2509 LAKEVIEW CR

19313105

4/15/08

marliwr

Groundwater and Wastewater Services File Imaging Project

May 2007

Barcode Font = IDAutomationHC39M

SERVICE REQUEST/WORK ORDER

D40

File 1401A

Log No.: _____ Section: DNWS Hazard? [ ] Yes [ ] No

Date: 3/18/97 Parcel: 193-131-05 <60 Days? [ ] Yes [ ] No

REQUESTING PERSON: Craig Pacenti Phone 345-2099

Address _____ City _____ Zip _____

PROPERTY CONCERNED: Facility Name _____


Address 2509 Lakeview Circle City _____ Zip _____

SERVICE REQUESTED: malfunction

ASSIGNED TO: L. Mialik TAKEN BY: L. Mialik

DATE	ACTIVITY REPORT
3/18/97	PC w/ Mr Pacenti.
3/24/97	OSV. Mr + Mrs Pacenti present. Advised to have S.T. contractor contact me. Effluent surfacing @ beginning of 3rd line (closest to house), alarm inoperable.
4/3/97	OSV. Mr + Mrs Pacenti present & David Jordan, registered S.T. contractor. D Box uncovered - 3rd line receiving most effluent; Mr Jordan installed speed leveler @ D Box to cut flow to 3rd line. Per Mr Jordan, will provide tank alert & check high water alarm/replace if necessary.
4/7/97	Vm message from Mr Pacenti - tank alert hooked up.
4/9/97	OSV. Mr + Mrs Pacenti present. Observed tank alert in garage - alarm operable. Area of malfunction appears to be drying up. Advised. JBM

No repair approval (permit) required.



NOTIFICATION TO REQUESTING PERSON: ( ) Written ( ) Verbal ( ) Not Applica

COMPLETED BY: Linda B. Mialik, RS , 4/9/97

REVIEWED BY: _____ /