Date Received 4-25-77

MECK COUNTY DEPARTMENT OF
RECEIVED
APR 25 1977
ENVIRONMENTAL HEALTH

APT No. 12265

T. C. No. 109-263-24

Map Date ---

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Midwood Realestate CORP
(LAST FIRST MIDDLE)

2) ADDRESS OF OWNER 2004 Belvedere Ave. Charlotte, NC ZIP 28205

3) PHONE NO. Home 376-4501 Office


4) LOCATION OF PROPERTY Marlwood CIRCLE
(STREET OR COUNTY ROAD)

5) SUBDIVISION Marlwood Acres LOT NO. 19 BLOCK NO. B

MAP BOOK NO 109 PAGE NO. 26

6) DEED REFERENCE DEED BOOK PAGE NO.

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

Lawrence A Sneffin
OWNER

EHD-5-76

Environmental Health Department's Copy

SOIL INVESTIGATION REPORT

Date of Investigation 4-26-77 APT NO. 12265

Owner Richard Realestate Corp. T.C. 107-263-24

Location of Property Westwood Circle Lot #14

Soil Suitability Ratings


Soil Properties	Soil 1	Soil 2	Soil 3	Soil 4
1. Soil Series	Tonkoll			
2. Soil Slope	Suitable 2-6%			
3. Soil Depth	unsuitable L36"			
4. Soil Texture	unsuitable 2-1 Expanding Clay			
5. Soil Structure	unsuitable Massive			
6. Restrictive Horizons	-			
7. Soil Drainage	Unsuitable Perched High water Table			
8. Soil Permeability (Percolation Rate)	unsuitable slow 720 min/in			
9. Other				
10. Overall Rating	unsuitable			

Remarks
Recommendations Based on this investigation, the soil on the lot was found to be unsuitable for installation of a septic tank system.

William A. Marlow

WAM

DIAGRAM OF PROPERTY



3/18/75

[illegible]'559

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

DATE ISSUED
1. 5-16-77
2. _____
3. _____

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

SIP NO. 12265
T.C. NO. 109-263-26
M P DATE _____

NAME OF OWNER Midwood Real Estate Corporation

ADDRESS OF OWNER 2004 Belvedere Ave., Charlotee, N.C. 28205

LOCATION OF LOT Marlwood CircleLot 19, Block B

The lot described above is not recommended for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge due to the following:

Soil Permeability Unsuitable.

Percolation rate in excess of 200 min/in.

John R. Adkisson

John R. Adkisson, Environmentalist
On Premises Waste Disposal Section

JRA: glr

(Stencil No.)
ENH 399
8/74

FORM NO.
H-11-8-21-74

R