

2016 KIMWAY DR

21518212

4/15/08

marliwr

Groundwater and Wastewater Services File Imaging Project
May 2007
Barcode Font = IDAutomationHC39M

SERVICE REQUEST/WORK ORDER

Log No.: 1116 A Section: IWWS Hazard? [ ] Yes [ ] No

Date: 4/2/97 Parcel: 215-182-12 (215-112-60 old?) <60 Days? [ ] Yes [ ] No

REQUESTING PERSON: Gregory Gaddy Phone (w) 577-8175 (h) 847-9425

Address _____ City _____ Zip _____

PROPERTY CONCERNED: Facility Name Same

Address 2016 Kimway Dr City _____ Zip _____


SERVICE REQUESTED: M alfunction

Per Mr Gaddy - tried to repair washer(?) bid himself approx 1 year by installing drain off pipe to woods line.

ASSIGNED TO: L. Mialik TAKEN BY: L Mialik

Retain as part of file

DATE	ACTIVITY REPORT
4/3/97	OSV. Gregory Gaddy present. Per probing of sewage disposal system S.T. under deck, brick storage building appears to have been constructed over portion of nitrification lines. Appears overflow pipe installed/hooked into 4th/last line. Unable to locate D-Box. Advised owner.
4/4/97	PC w/Mr Gaddy - will contact David Jordan (registered S.T. contractor) to meet on site; house will be sold + money escrowed should repair be necessary.
4/7/97	OSV. Mr Gaddy + David Jordan present. D Box uncovered - flow cut to 4th/last line. (had been receiving most of the effluent as best as could be determined). Portion of overflow pipe + the gravel around it removed with backhoe + soil packed back in. Recommended that S.T. be pumped. No repair approval/permit required at this time. JBM



NOTIFICATION TO REQUESTING PERSON: ( ) Written (✓) Verbal ( ) Not Applicable

COMPLETED BY: Jba B. Mialik, RS, 4/7/97

REVIEWED BY: _____