Date Received 8-18-82

APT No. 18938

T. C. No 031-114-05

Map Date

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Medlin (LAST) Marvin (FIRST) J. (MIDDLE)

2) ADDRESS OF OWNER 107 McCaskey RD. Williamston, N.C. ZIP 27892

3) PHONE NO. Home None Office 919 792 8161

4) LOCATION OF PROPERTY 1216 Mt. Holly Huntersville Rd. Charlotte, N.C. (STREET OR COUNTY ROAD)


5) SUBDIVISION No LOT NO. BLOCK NO.

MAP BOOK NO PAGE NO. Tax # 031-114-05

6) DEED REFERENCE DEED BOOK 2579 PAGE NO 473

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge

For any questions call Century 21 Westside Realty 399 4848 Harry Rudolph or Joel Murphy



7) ACCURATELY DIAGRAM & DIMENSION LOT

Marvin J. Medlin
OWNER

EHD-5-76

Environmental Health Department's Copy

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE NORTH CAROLINA 28203

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION
EFFLUENT DISCHARGE

S.I.R. # 18938

T. C. # 031-114-05

DATE: 8-24-82

NAME OF OWNER Medlin, Marvin J.

ADDRESS OF OWNER 107 McCaskey Rd., Williamston, NC 27892

LOCATION OF LOT 1216 Mt.Holly-Huntersville Road

As determined under the Rules and Regulations promulgated by the Commission for Health Services, Division of Health Services, North Carolina Department of Human Resources, Raleigh, North Carolina, the soils on the lot described above were found to have a limited area of provisionally suitable soils. Please submit plot plans of proposed residence, septic tank system, and well location.

SOIL TEXTURE (2-1 clay)	UNSUITABLE
SOIL STRUCTURE (massive)	UNSUITABLE
SOIL DEPTH (2 feet)	UNSUITABLE
SOIL DRAINAGE/GROUNDWATER (slow)	UNSUITABLE

Mike Sexton

Michael A. Sexton, Environmentalist
On Premises Waste Disposal Section

DEPARTMENT OF ENVIRONMENTAL HEALTH
MECKLENBURG COUNTY, NORTH CAROLINA

SITE EVALUATION

S.I.R. NO. 18938

T.C. NO. 031-114-05

(Ground Absorption Sewage Disposal)

OWNER: MARVIN J. MEDLIN
ADDRESS: 107 McII CASKEY Rd
Williamston NC. 27892
PLAT NO:
LOT SIZE: 4A
LOCATION OF SITE: Mt Holly Huntersville Rd

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	S (PS) U 2-10	S (PS) U 2-10	S PS U	S PS U
2. SOIL TEXTURE (12-36 inches) Sandy, Loamy, Clayey (Note 2-1 Clay)	S PS (U) 2-1 clay	S PS (U) mix Clay	S PS U	S PS U
3. SOIL STRUCTURE (12-36 inches)	S PS (U) Massive	S PS (U) Massive	S PS U	S PS U
4. SOIL DEPTH (inches)	S PS (U) 2 feet	S PS (U) 36"	S PS U	S PS U
5. RESTRICTIVE HORIZONS (Inches) (Impervious strata, Rock)	S PS (U) Clay	S PS (U) Clay	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (external and internal)	S PS (U) slow	S PS (U) slow	S PS U	S PS U
7. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U
8. SOIL GROUP	II b	II b		
9. SITE CLASSIFICATION	Unsuitable	Unsuitable		
10. SOIL SERIES	Enon	Helena		

S - Suitable PS - Provisionally Suitable U - Unsuitable

**See Diagram on Back (includes: soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slopes)

Recommendations/Comments: See Map For Soil Depth & Perched Water table Depth.

Described by: W B Sawyer
Title: Soil Scientist

Date: 8-23-82

EHD 539 (Revised: 6/82)

2

Mt. Holly Huntersville Rd

