Date Received 8/23/79

APT No. 1611 C

T. C. P.O. No. 105-131-09810

Map Date _____

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

THOMAS + Todd Realty

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER ROGERS, GWEN D. (MRS)
LAST FIRST MIDDLE

2) ADDRESS OF OWNER 2301 Radcliff Ave ZIP 29207

3) PHONE NO Home 376-2197 Office _____


4) LOCATION OF PROPERTY Plaza Rd Ext at Plaza Park Drive
STREET OR COUNTY ROAD

5) SUBDIVISION Survey of 22 March 74 LOT NO B BLOCK NO. _____

MAP BOOK NO _____ PAGE NO _____

6) DEED REFERENCE DEED BOOK _____ PAGE NO _____

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface soil absorption effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

Gwen D. Rogers
OWNER By: Randy Todd (365-0615)

EHD-5-76

Environmental Health Department's Copy

II

NORTH CAROLINA
DEPARTMENT OF HUMAN RESOURCES
DIVISION OF HEALTH SERVICES
RALEIGH, NORTH CAROLINA

APPENDIX II
SITE EVALUATION

S. I. R. NO. 16116
T. C. # PO 105-131-10

(Ground Absorption Sewage Disposal)

OWNER: GWEN ROGERS
ADDRESS: 4301 Radcliffe Ave
COUNTY: CHARLOTTE, 28207
LOCATION OF SITE: PLAZA Rd EXT. AT PLAZA PARK DRIVE Lot B

DATE REQUESTED: 8-23-79
PLAT NO.:
LOT SIZE: 3500 Sq Ft

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	S PS 0-4 (U)	S PS U	S PS U	S PS U +
2. SOIL TEXTURE (12-36 in.) (Sandy, loamy, clayey, Note 2:1 Clay)	S (PS) Loamy Clayey U	S PS U	S PS U	S PS U
3. SOIL STRUCTURE (12-36 in.) (Clayey Soils)	S (PS) Blocky U	S PS U	S PS U	S PS U
4. SOIL DEPTH (In.)	S (PS) 48> U	S PS U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (In.) (Impervious Strata, Rock)	S PS May Be some Deep (U)	S PS U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (External & internal)	S PS Seepage To Flooding (U)	S PS U	S PS U	S PS U
7. SOIL PERMEABILITY (Percolation Rate)	S PS Slow (U)	S PS U	S PS U	S PS U
8. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U
9. SITE CLASSIFICATION	Unsuitable			
SOIL SERIES	MONOCAN-Cecil			

S - Suitable PS - Provisionally Suitable U - Unsuitable


* See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies wet areas, fill areas, wells, water bodies, slope patterns, etc

Recommendations/Comments: MAIN Problem SEEM To Be Caused By Water Being Dammed By Rd

Described By: W. B. Ramsey
Title: Soil scientist Date: 8-28-79

DHS Form 2601
Sanitation
EHD 539 (3/79)

2


119
PONDED AREA
Cecil & MOMOCAN
200

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

SIR. NO. 16116
T.C. NO. po 105-131-09, 10
MAP DATE
DATE 8/31/79

NAME OF OWNER Rogers, Gwen D. (Mrs.)

ADDRESS OF OWNER 2301 Radcliff Avenue, Charlotte, NC 28207

LOCATION OF LOT Plaza Road extension at Plaza Park Drive Lot B

As determined under the Rules and Regulations promulgated by the Commission for Health Services, Division of Health Services, North Carolina Department of Human Resources, Raleigh, North Carolina, the soils on the lot described above were found to be unsuitable for the installation of an individual septic tank - soil absorption system. This site cannot be approved for a septic tank system due to the following reason:

Soil Drainage/Groundwater Unsuitable
Soil Permeability Unsuitable

John R. Adkisson

John R. Adkisson, Environmentalist

R