Date Received 6/6/79

RECEIVED
JUN 1 1979
ENVIRONMENTAL HEALTH

APT No 15709
T. C. No. R0132-132-08
Map Date

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER (LAST) Colonial Service Corporation (FIRST) (MIDDLE)

2) ADDRESS OF OWNER P. O. Box 10 Monroe, N. C. ZIP 28110

3) PHONE NO Home Office 372-0763


4) LOCATION OF PROPERTY N. C. #51 Mint Hill, N. C. (STREET OR COUNTY ROAD) Goldsmith Ln

5) SUBDIVISION Bainbridge LOT NO 43 BLOCK NO.

MAP BOOK NO 18 PAGE NO 347 & 348

6) DEED REFERENCE DEED BOOK PAGE NO

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

OWNER

EHD-5-76

Environmental Health Department's Copy

NORTH CAROLINA
DEPARTMENT OF HUMAN RESOURCES
DIVISION OF HEALTH SERVICES
RALEIGH, NORTH CAROLINA

APPENDIX H
SITE EVALUATION

S.I.R. NO. 15709
T.C. P0 137-132-08

(Ground Absorption Sewage Disposal)

OWNER: COLONIAL SERVICE CORP. DATE REQUESTED: 5-17-79
ADDRESS: PO BOX 10 MONROE, N.C. PLAT NO.:
COUNTY: UNION 28110 LOT SIZE: 32929
LOCATION OF SITE: BLAIR RD. BAIN BRIDGE Cold Smith Bear lot 43

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	S PS 0-3 (U)	S PS U	S PS U	S PS U +
2. SOIL TEXTURE (12-36 in.) (Sandy, loamy, clayey, Note 2:1, Clay)	S (PS) Loamy U	S PS U	S PS U	S PS U
3. SOIL STRUCTURE (12.36 in.) (Clayey Soils)	S Weak (PS) Blocky U	S PS U	S PS U	S PS U
4. SOIL DEPTH (In.)	S PS >48 (U)	S PS U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (In.) (Impervious Strata, Rock)	S (PS) None U	S PS U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (External & Internal)	S Slow PS (U) Flood Plain	S PS U	S PS U	S PS U
7. SOIL PERMEABILITY (Percolation Rate)	S PS (U) Slow	S PS U	S PS U	S PS U
8. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U
9. SITE CLASSIFICATION	Unsuitable			
SOIL SERIES	MONOCAN			

S - Suitable PS - Provisionally Suitable U - Unsuitable


* See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slope patterns, etc)

Recommendations/Comments: _____

Described By: W. B. Ramsey
Title: Soil Scientist Date: 6-19-79

DHS Form 2601 (2/77)
Sanitarian

3


Lot 43
222
125
MONOCAD
6—3
316
Gold Smith Lane

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

15709

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

SIR.NO. _____
T.C. NO. _____ 132-08
MAP DATE _____
DATE July 2, 1979

NAME OF OWNER Colonial Service Corp

ADDRESS OF OWNER PO Box 10, Monroe, NC 28110

LOCATION OF LOT Goldsmith Lane, Lot 43

As determined under the Rules and Regulations promulgated by the Commission for Health Services, Division of Health Services, North Carolina Department of Human Resources, Raleigh, North Carolina, the soils on the lot described above were found to be unsuitable for the installation of an individual septic tank-soil absorption system. This site cannot be approved for a septic tank system due to the following reason:

Soil Drainage to Groundwater Unsuitable

Soil Permeability Unsuitable

John R. Adkisson, Environmentalist

MED 398
7/77

R