Date Received 5/16/77

MECK COUNTY DEPARTMENT OF
RECEIVED
MAY 16 19:7

APT No. 12382

T C. No. [illegible]

Map Date [illegible]

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER [illegible] (LAST / FIRST / MIDDLE)

2) ADDRESS OF OWNER [illegible] ZIP [illegible]

3) PHONE NO Home [illegible] Office [illegible] 376 5560 or 831-7626


4) LOCATION OF PROPERTY [illegible] DRIVE ([illegible] PARALLEL NOT TO GRAY FOX ROAD)
STREET OR COUNTY ROAD

5) SUBDIVISION [illegible] LOT NO 7 BLOCK NO 191

MAP BOOK NO ~~2095~~ 211 PAGE NO ~~127~~ 191

6) DEED REFERENCE DEED BOOK 2095 PAGE NO 417

Application is hereby made to the Mecklenburg County Department of Environmental Health for the [illegible] duct [illegible] investigation [illegible] of the [illegible] described below for the purpose [illegible] site [illegible] system with [illegible] surface [illegible] absorption [illegible] effluent [illegible] age.



7) ACCURATELY DIAGRAM & DIMENSION LOT

OWNER [signature]

EHD 5-76

Environmental Health Department's Copy

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE NORTH CAROLINA 28203

DATE ISSUED
1. 5-25-77
2. _____
3. _____

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

SIR No. 12382
T.C. No. 211-191-07
L.P. No. _____

NAME OF OWNER: **Pinson, Walter Eugene**

ADDRESS OF OWNER: **2801 Alexander Ave., Kannapolis, NC 28081**

LOCATION OF LOT: **Merrymount Drive, Lot 7, Block 191**

The lot described above is not recommended for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge due to the following:

Soil Permeability Unsuitable.

Percolation rate in excess of 200 min/in.

John R. Adkisson

John R. Adkisson, Environmentalist
On Premises Waste Disposal Section

JRA: glr

(Stencil No.)
EHS 339
8/74

SOIL INVESTIGATION REPORT

Date of Investigation May 19 1975 APT NO. 12382

Owner Walter E. Kinson T.C. 311-19102

Location of Property Mungmount Ave. LOT #7

Soil Suitability Ratings

Soil Properties	Soil 1	Soil 2	Soil 3	Soil 4
1. Soil Series	Mar Klinebury	Mar Klinebury gullied		
2. Soil Slope	Sat. table 0-10%	unsuitable complex slopes		
3. Soil Depth	unsuitable 24"	unsu. table Variable Depth		
4. Soil Texture	unsu. table 2-1 Expanding clay	unsuitable 2-1 Expanding Clay		
5. Soil Structure	unsu. table massive	unsu. table massive		
6. Restrictive Horizons				
7. Soil Drainage	Sat. table water Table 20'	Sat. table water Table 20'		
8. Soil Permeability (Percolation Rate)	unsuitable slow 72+ min/in	unsuitable slow 72+ min/in		
9. Other				
10. Overall Rating	unsu. table	unsuitable		


Remarks ~~Recommendations~~ Based on the investigation, this lot was found to be unsuitable for the installation of a septic tank system.

See diagram on back

William R. Martin
Soil Scientist

3/18/75
EHS 539

DIAGRAM OF PROPERTY



3/18/75
EHD 539