

NO PARCEL WITH ADDRESS OF 14210 SOLDIER ROAD
LOCATED NOR CAN IT BE TRACED BY PROPERTY OWNER

8/14/08

marliwr

Groundwater and Wastewater Services File Imaging Project
May 2007
Barcode Font = IDAutomationHC39M

199-086.12 17800
1985

Mecklenburg County
Health Department

February 25, 1992

Mr. Timothy Glenn Cox
14210 Soldier Road
Charlotte, NC 28278

Dear Mr. Cox:

At your realtor's request, an investigation was made of the septic tank system and a well water sample was collected on the property located at 14210 Soldier Road, Charlotte, N.C. (tax parcel number 199-086-12) on February 19, 1992.

At the time of the investigation there was no effluent apparent on the surface of the ground; However, it appears a graveled parking area has been located over a portion of the septic drainfield.

Approximately forty (40%) of effluent is dissipated through evapotranspiration from the drain lines. This treatment is lost by driving or compacting the soil cover over the nitrification trenches.

Law and Rules for Sanitary Sewage Collection, Treatment, and Disposal, 15A NCAC 18A .1900, Section .1950 (c) requires "Nitrification fields and repair areas shall not be located under paved areas or areas subject to vehicular traffic."

All parking should be re-directed immediately to the original designated parking area; continued parking over the drainfield may result in a failure to the septic system. A copy of the septic permit showing the approved driveway is enclosed for your review.

The laboratory analysis of the well water sample was reported to be positive for coliform bacteria. The presence of bacteria indicates a source of contamination. It is recommended that the well be chlorinated. The procedure for chlorination of a well is enclosed.

If You have any questions concerning this matter, please contact me at 336-5571 between 4:00-5:00 p.m.

Sincerely,

Judy J. Kiser R.S.

Judy J. Kiser, R.S.
Individual Water and Wastewater Systems

Enclosures (2)