Date Received 2-19-74

APT No 7417

T C No

Map Date

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

RECEIVED 1974

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER Carpenter (LAST) John L and (FIRST) Austin C's (MIDDLE)

2) ADDRESS OF OWNER P.O. Box 2335 Charlotte NC ZIP 28234

3) PHONE NO Home 392-4761 Office 392-4761


4) LOCATION OF PROPERTY Mountain View Drive (STREET OR COUNTY ROAD) off Beatties Ford Road

5) SUBDIVISION Mountain View Heights LOT NO 26 BLOCK NO

MAP BOOK NO 11 PAGE NO 243

6) DEED REFERENCE DEED BOOK PAGE NO

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

John L Carpenter & C's Austin
OWNER
By John L Carpenter

FORM NO E-1-9-1-72

HEALTH DEPARTMENT'S COPY

MECKLENBURG COUNTY
Department of Public Health

1200 Blythe Boulevard
Charlotte, North Carolina 28203
Telephone 374-2113

Date Issued
1. 2-26-74
2. _____
3. _____

SDR No. 7897
T.C. No. 071-083-03
-1-72

SITE DISAPPROVAL REPORT
INDIVIDUAL SEPTIC TANK SYSTEM WITH SUBSURFACE,
SOIL ABSORPTION, EFFLUENT DISCHARGE

NAME OF OWNER Carpenter, John L.

ADDRESS OF OWNER P.O. Box 2336, Davidson, N.C. ZIP _____

LOCATION OF LOT Mountainview Drive, Lot 26

The lot described above has been disapproved for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge due to the following:

FAILURE TO PASS PERCOLATION TEST (60 minutes per inch or less)

	Test No.	Date of Test	Percolation Rate
____	1.	_____	_____ min/in
____	2.	_____	_____ min/in
____	3.	_____	_____ min/in

X ON SITE INSPECTION REVEALED LOT TO BE UNSUITABLE FOR THE FOLLOWING REASON(S) 2-25-74 Soils were found to be a shallow phase of the Pacolet series. These soils are extremely shallow to rock material. The depth to rock varies from 5 to about 4 feet. These soil characteristics impose extreme physical limitations on the installation of sy[illegible] potential for lateral seepage of effluent resulting in the wastes coming to the soil surface.

Soil Scientist

Environmentalist

(Stencil No.)
EHD 398
8/70

FORM NO.
E-19-8-14-70