

7815 DAVID KENNEY FARM RD

00916107

7/1/08

marliwr

Groundwater and Wastewater Services File Imaging Project
May 2007
Barcode Font = IDAutomationHC39M

Mecklenburg County
Health Department

August 10, 1995

Mr. Tommy Cross
7815 David Kennyfarm Road
Huntersville, NC 28078

Re: 7815 David Kenny Farm Road
File: 12464
Parcel: 009-161-07

Dear Mr. Cross:

A site visit was made to your residence for the purpose of determining if the proposed pool would interfere with your septic tank system. At that time, we discussed that a driveway had been installed over a portion of your septic tank drainfield. This is in violation of Laws and Rules for Sewage Treatment and Disposal Systems 15A NCAC 18A .1900, .1950 (c), which states "Nitrification fields and repair areas shall not be located under paved areas or areas subject to vehicular traffic. "Approximately forty percent of the effluent in a sewage disposal system is dissipated through evapotranspiration from the drain lines. This treatment is lost with construction and compaction over the drainfield. Repair area was still available on this property.

Please be aware that if the septic tank system malfunctions causing effluent to surface to the top of the ground then you must immediately correct the situation. An Improvement Permit for repair must be secured from the Mecklenburg County Health Department prior to repair of a septic tank system. Pumping out the tank contents by a registered septage hauler is considered maintenance of the system.

If you have any questions concerning this matter, please contact me at 336-5569.

Sincerely,

Susan Bateman

Susan M. Bateman, R.S.
Individual Water and Wastewater Systems

SB:gf

Mr. Tommy Cross
7815 David Kenny Farm Road
Huntersville, NC

Re: 7815 David Kenny Farm Rd.
File: 12464
Tax Parcel: 009-161-07

Dear Mr. Cross:

A site visit was made to your residence for the purpose of determining if the proposed pool would interfere with your septic tank system. At that time, we discussed that ~~a portion of your septic tank drainfield has had~~ a driveway has been installed over a portion of your septic tank drainfield. This is in violation of Laws and Rules for Sewage Treatment and Disposal Systems 15A NCAC 18A .1900, ~~which states~~ .1950(c), which states "Nitrification fields and repair areas shall not be located under paved areas or areas subject to vehicular traffic." Approximately forty percent of the effluent in a ~~Repair area was still available on this property.~~ sewage disposal system is dissipated through evapotranspiration from the drain lines. This treatment is lost with construction and compaction over the drainfield. Repair area was still available on this property.

Please be aware that if the septic tank system malfunctions causing effluent to surface to the top of the ground then you must immediately correct the situation. An Improvement Permit for repair must be secured from the Mecklenburg County Health Department prior to repair of a septic tank system. Pumping ~~the~~ out the tank contents by a registered septage hauler is considered maintenance of the system.

16/40