Date Received 5/11/77

APT No 12447

T. C. No

Map Date

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER BOB McLEMORE & CO., INC.
(LAST FIRST MIDDLE)

2) ADDRESS OF OWNER P.O. Box 25746 CHAR. ZIP 28212

3) PHONE NO Home Office 545-6111


4) LOCATION OF PROPERTY SPOKESHAVE LN.
(STREET OR COUNTY ROAD)

5) SUBDIVISION PROVIDENCE RIDGE LOT NO. 18 BLOCK NO. 13

MAP BOOK NO PAGE NO.

6) DEED REFERENCE DEED BOOK PAGE NO.

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and on-site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface soil absorption effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

Peter L. Goebel
OWNER

FORM NO E[illegible]-3M-6-75

HEALTH DEPARTMENT'S COPY

SOIL INVESTIGATION REPORT

Date of Investigation May 19, 1977 APT NO. 12447

Owner Bob McKenzie & Co., Inc.

Location of Property Spokane Shore Lane lot no 18 Block B

Soil Suitability Ratings Tax Code No. 231 - 101-61


Soil Properties	Soil 1	Soil 2	Soil 3	Soil 4
1. Soil Series	Chewelah		Pacific	
2. Soil Slope	—		unsuitable >30%	
3. Soil Depth	—		unsuitable <48"	
4. Soil Texture	—		provisionally suitable clay	
5. Soil Structure	—		provisionally suitable blocky	
6. Restrictive Horizons	—		—	
7. Soil Drainage	unsuitable poorly drained		suitable water table >6'	
8. Soil Permeability (Percolation Rate)	unsuitable seasonal high water table & slow		provisionally suitable moderate	
9. Other	unsuitable surface flooding		Comm/ind inadequate area	
10. Overall Rating	unsuitable		provisionally unsuitable	

Recommendations Based on this investigation, the soils were found to be unsuitable for installation of a septic tank system.

[redacted] Edward Casement

3/75
FD 559

DIAGRAM OF PROPERTY



3/18/75
EHD 559

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE NORTH CAROLINA 28203

DATE ISSUED
1. 5-25-77
2. _____
3. _____

SOIL EVALUATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
[illegible]
EFFLUENT DISCHARGE

SIR NO. 12447
T.O. NO. P.O.231-101-01
L.P. NO. _____

NAME OF OWNER: Bob McLemore & Company, Inc.

ADDRESS OF OWNER: P.O. Box 25746, Charlotte, NC 28212

LOCATION OF LOT: Spokeshave Lane, Lot 18, Block B

The lot described above is not recommended for the installation of an individual septic tank system with subsurface soil absorption, effluent discharge due to the following:

Soil Permeability Unsuitable.

Inadequate area of suitable soils.

John R. Adkisson, Environmentalist
On Premises Waste Disposal Section

JRA: glr

(Stencil No.)
EHD 389
8/74

[illegible]
5-25-77

Date Received 5/16/77

APT No. 12447

T. C. No.

Map Date

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER BOB McLEMORE & CO., INC.
(LAST FIRST MIDDLE)

2) ADDRESS OF OWNER P.O. Box 25746 CHAR. ZIP 28212

3) PHONE NO. Home Office 545-6111


4) LOCATION OF PROPERTY SPOKESHAVE LN.
(STREET OR COUNTY ROAD)

5) SUBDIVISION PROVIDENCE RIDGE LOT NO 18 BLOCK NO. B

MAP BOOK NO PAGE NO.

6) DEED REFERENCE DEED BOOK PAGE NO.

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and on-site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

Peter L. Gobel
OWNER

FORM NO. EH-11-3M-6-75

HEALTH DEPARTMENT'S COPY

SOIL INVESTIGATION REPORT

Date of Investigation May 19, 1977 APT NO. 12447

Owner Bob McLaurin & Co., Inc.

Location of Property Spokane Acres Lot No 18 Block B

Soil Suitability Ratings Tax Code No 10 231 - 101-01

Soil Properties	Soil 1	Soil 2	Soil 3	Soil 4
1. Soil Series	Chewelah		Pacific	
2. Soil Slope	—		unsuitable >30%	
3. Soil Depth	—		unsuitable <48"	
4. Soil Texture	—		provisionally suitable clay	
5. Soil Structure	—		provisionally suitable blocky	
6. Restrictive Horizons	—		—	
7. Soil Drainage	unsuitable poorly drained		suitable water table >6'	
8. Soil Permeability (Percolation Rate)	unsuitable seasonal high water table 6" from		provisionally suitable moderate	
9. Other	unsuitable surface Floods		60 min/in unsuitable rock	
10. Overall Rating	provisionally Suitable		provisionally unsuitable	


Recommendations Based on this investigation, the soils were found to be unsuitable for installation of a septic tank system.

Site Map

Sanitarian

3/10/75

DIAGRAM OF PROPERTY



3/18/75
EHD 539

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE NORTH CAROLINA 28203

DATE ISSUED
1. 5-25-77
2. _____
3. _____

SEWER AND SOIL EVALUATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
INCL. SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

SIR NO. 12447
T.C. NO. P.O.231-101-01
LOT NO. _____

NAME OF OWNER Bob McLemore & Company, Inc.

ADDRESS OF OWNER P.O. Box 25746, Charlotte, NC 28212

LOCATION OF LOT Spokeshave Lane, Lot 18, Block B

The lot described as above is not recommended for the installation of an individual septic tank system with subsurface soil absorption, effluent discharge due to the following:

Soil Permeability Unsuitable.

Inadequate area of suitable soils.

John R. Adkisson, Environmentalist
On Premises Waste Disposal Section

JRA: glr

(Stencil Co.)
EHD 388
8/74

FORM NO.
T-21-8-21-74