Date Received 3-5-73

APT No. 5698

T C. No

Map Date

Mail to Charles E. Thrower 2140 Wayland Ave Wayland 28208

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER Joy (LAST) Tommy (FIRST) A. (MIDDLE)

2) ADDRESS OF OWNER Rt. 6 Box 608-T, Charlotte, N.C. ZIP 28208

3) PHONE NO Home 392-9878 Office


4) LOCATION OF PROPERTY Marita Drive (STREET OR COUNTY ROAD)

5) SUBDIVISION Woodlea LOT NO 6 BLOCK NO. D

MAP BOOK NO 12 PAGE NO 281

6) DEED REFERENCE DEED BOOK 2790 PAGE NO 315

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and on on site inspection of the lot here nabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

Tommy A Joy
OWNER

FORM NO E-1-9-1-72

HEALTH DEPARTMENT'S COPY

MECKLENBURG COUNTY
Department of Public Health
1200 Blythe Boulevard
Charlotte, North Carolina 28203

Telephone 374-2113

Date Issued
1. April 2, 1973
2. _____
3. _____

SDR No. 5698
T.C. No. _____

SITE DISAPPROVAL REPORT
INDIVIDUAL SEPTIC TANK SYSTEM WITH SUBSURFACE,
SOIL ABSORPTION, EFFLUENT DISCHARGE

NAME OF OWNER Joy, Tommy A.

ADDRESS OF OWNER Route 6, Box 608-T ZIP 28208

LOCATION OF LOT Marita Drive, Lot 6-D

The lot described above has been disapproved for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge due to the following:

FAILURE TO PASS PERCOLATION TEST (60 minutes per inch or less)

	Test No.	Date of Test	Percolation Rate
X	1.	3-30-73	180 min/in
____	2.	_____	_____ min/in
____	3.	_____	_____ min/in

____ ON SITE INSPECTION REVEALED LOT TO BE UNSUITABLE FOR THE FOLLOWING REASON(S) _____

John R. Atkinson
Environmentalist

(Stencil No.)
HHD 398

FORM HD.
8-19-8-14-70

SOIL INVESTIGATION REPORT

Date of Investigation FEBURARY 6, 1976 APT NO. 5698

Owner C.D. Stephens

Location of Property Marita Drive, lot no. 6 Block D

Soil Suitability Ratings Tax Code No. 631-656-05

Soil Properties	Soil 1	Soil 2	Soil 3	Soil 4
1. Soil Series	INON			
2. Soil Slope	acceptable 2-6%			
3. Soil Depth	acceptable 48"			
4. Soil Texture	unacceptable 2:1 EXPANDING clay			
5. Soil Structure	unacceptable massive			
6. Restrictive Horizons	—			
7. Soil Drainage	unacceptable perched high water table			
8. Soil Permeability (Percolation Rate)	unacceptable >200 min/in			
9. Other	—			
10. Overall Rating	unacceptable			


Recommendations Based on this investigation, the lot is not recommended for approval for installation of a septic tank system.

See diagram on back

W. Edward Casavant
Soil Scientist

WEC
3/18/75
EHC 539

DIAGRAM OF PROPERTY



3/18/75

END 539

MECKLENBURG COUNTY
Department of Public Health
1200 Blythe Boulevard
Charlotte, North Carolina 28203

DATE ISSUED
1. 2/10/76
2. _____
3. _____

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

SIP NO. 5698
T.C. NO. 031-056-05
M.P. DATE -

NAME OF OWNER Stephens Carà Douglas

ADDRESS OF OWNER 2110 Little Roak Road, Charlotte, N. C. 2821[illegible]

LOCATION OF LOT Marita Drive, Lot [illegible], Block D, Woodlea Subdivision

The lot described above is not recommended for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge due to the following:

Unsuitable Soil

Percolation rate in excess of 200 min./in.

John R. Adkisson

John R. Adkisson, Environmentalist
On Premises Waste Disposal Branch
Environmental Health Department

JRA:jjk

(Stencil No.)
EHD 388
8/74

FORM NO.
E-19-8-21-74