Date Received _____

APT No 16147

T. C. No ~~[illegible]~~

Map Date _____

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER DANCY HOMES, INC., (LAST / FIRST / MIDDLE)

2) ADDRESS OF OWNER 1443 South Boulevard, Charlotte, N.C., 28203 ZIP _____

3) PHONE NO. Home _____ Office 332-6310 or 334-2706


4) LOCATION OF PROPERTY DANCY DRIVE (OFF MARGARET WALLACE ROAD) (STREET OR COUNTY ROAD)

5) SUBDIVISION _____ LOTS NO. 8 & 9 BLOCK NO. _____

MAP BOOK NO. _____ PAGE NO _____

6) DEED REFERENCE DEED BOOK _____ PAGE NO. _____

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



MARGARET WALLACE ROAD

) ACCURATELY DIAGRAM & DIMENSION LOT

DANCY HOMES INC.,

[signature]

OWNER

FORM NO. E-1-8-1-72

HEALTH DEPARTMENT'S COPY

NORTH CAROLINA
DEPARTMENT OF HUMAN RESOURCES
DIVISION OF HEALTH SERVICES
RALEIGH, NORTH CAROLINA

APPENDIX II
SITE EVALUATION

S. I. R. NO. 16144

T. C. # P.O. 193-043-25
Lot 849

(Ground Absorption Sewage Disposal)

OWNER: DANCY HOMES, INC., DATE REQUESTED: 8-28-79
ADDRESS: 1443 S. BLVD. PLAT NO.:
COUNTY: CHARLOTTE, N.C. 28203 LOT SIZE: 20,000 ±
LOCATION OF SITE: DANCY Drive Lot 849 Combined

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	(PS) 2–10	(PS) 2–10	S PS U	S PS U
2. SOIL TEXTURE (12-36 in.) (Sandy, loamy, clayey, Note 2:1 Clay)	PS (U) Clayey 2-1	PS (U) Clayey 2-1	S PS U	S PS U
3. SOIL STRUCTURE (12-36 in.) (Clayey Soils)	PS (U) Massive	PS (U) Massive	S PS U	S PS U
4. SOIL DEPTH (In.)	PS (U) <48	PS (U) <48	S PS U	S PS U
5. RESTRICTIVE HORIZONS (In.) (Impervious Strata, Rock)	PS (U) Clays	PS (U) Clays	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (External & Internal)	PS (U) Slow	PS (U) Very Slow	S PS U	S PS U
7. SOIL PERMEABILITY (Percolation Rate)	PS (U) Slow	PS (U) Slow	S PS U	S PS U
8. OTHER (Specify)	Unsuitable		S PS U	S PS U
9. SITE CLASSIFICATION	Unsuitable	Unsuitable		
SOIL SERIES	VANCE	ENON		

S - Suitable PS - Provisionally Suitable U - Unsuitable

* See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies wet areas, fill areas, wells, water bodies, slope patterns, etc


Recommendations/Comments:

Described By: W. B. Ramsey

Title: Soil Scientist Date: 9-11-79

DHS Form 2601
Sanitation
EHD 539 (3/79)

2


ENON
2-10
Area
* Total Area May NOT Be Exact. Application & Drawing Unclear.
100
LOT 8
Lot 9
Area
VANCE
2-10
100
100
DARCY DRIVE
MARGARET WALLACE RD

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

S.I.R. # 16144

T.C. # po 193-083-25

DATE Sept. 13, 1979

NAME OF OWNER Dancy, Sr. (Dancy Homes, Inc.)

ADDRESS OF OWNER 1443 South Boulevard, Charlotte

LOCATION OF LOT Dancy Drive, Lots 8 and 9

As determined under the Rules and Regulations promulgated by the Commission for Health Services, Division of Health Services, North Carolina Department of Human Resources, Raleigh, North Carolina, the soils on the lot described above were found to be unsuitable for the installation of an individual septic tank - soil absorption system, due to the following reason:

Soil Structure Massive

Soil Permeability Unsuitable

John R. Adkisson

John R. Adkisson, Environmentalist

R