Date Received March 10, 1981

APT No 16149

T. C No 025-152-05

Map Date 1/79

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Harris (LAST) Edward (FIRST) Harris (MIDDLE) Jr.

2) ADDRESS OF OWNER 1913 N. Tryon Street ZIP 28206

3) PHONE NO. Home 364-3019 Office 333-4410


4) LOCATION OF PROPERTY Mt Holly - Huntersville Rd (STREET OR COUNTY ROAD)

5) SUBDIVISION Westminster Park #2 LOT NO 3 BLOCK NO B

MAP BOOK NO 11 PAGE NO 138

6) DEED REFERENCE DEED BOOK 2495 PAGE NO 128

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface soil absorption effluent discharge.



7) ACCURATELY DIAGRAM & DIMENSION LOT

Edward C. Harris Jr
E.C. Harris Pres
OWNER

EHO-5-76

Environmental Health Department's Copy

S. I. R. NO. 6141

NORTH CAROLINA
DEPARTMENT OF HUMAN RESOURCES
DIVISION OF HEALTH SERVICES
RALEIGH, NORTH CAROLINA

APPENDIX II
SITE EVALUATION

T. C. # 015-12105

(Ground Absorption Sewage Disposal)

OWNER: [illegible] D Warren
ADDRESS: 1113 Tech Wagon Rd.
COUNTY: Iredell
LOCATION OF SITE: [illegible]

DATE REQUESTED:
PLAT NO.: Lot 28
LOT SIZE: 2 acre

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	S 2 3 6 PS U	S PS U	S PS U	S PS U +
2. SOIL TEXTURE (12-36 in.) (Sandy, loamy, clayey, Note 2:1 Clay)	S sl PS c l U	S PS U	S PS U	S PS U
3. SOIL STRUCTURE (12-36 in.) (Clayey Soils)	S Moderate PS U	S PS U	S PS U	S PS U
4. SOIL DEPTH (In.)	S 48+ PS U	S PS U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (In.) (Impervious Strata Rock)	S None PS U	S PS U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (External & internal)	S Seasonal PS Perched Water Table U	S PS U	S PS U	S PS U
7. SOIL PERMEABILITY (Percolation Rate)	S 2 Slow PS U	S PS U	S PS U	S PS U
8. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U
9. SITE CLASSIFICATION	Unsuitable			
SOIL SERIES	Helena			

S - Suitable PS - Provisionally Suitable U - Unsuitable

* See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies wet areas, fill areas, wells, water bodies, slope patterns, etc.


Recommendations/Comments:

Described By: William R Warren

Title: Soil Scientist Date: 9-10-79

DHS Form 2601
Sanitation
EHD 539 (3/79)

2


100'
200'
100'

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE NORTH CAROLINA 28203

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

S.I.R. # 16149

T.C. # 025-152-05

DATE Sept. 10, 1979

NAME OF OWNER Harris, C.D.

ADDRESS OF OWNER 1713 North Tryon St., Charlotte 28206

LOCATION OF LOT Mt. Holly-Huntersville Rd., Westminister Park, lot 28

As determined under the Rules and Regulations promulgated by the Commission for Health Services, Division of Health Services, North Carolina Department of Human Resources, Raleigh, North Carolina, the soils on the lot described above were found to be unsuitable for the installation of an individual septic tank - soil absorption system, due to the following reason:

Soil Structure Massive

Soil Permeability Unsuitable

John R. Adkisson

John R. Adkisson, Environmentalist

R

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 Blythe Boulevard,
Charlotte, North Carolina 28203

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

S.I.R. # 16149

T.C. # 025-152-05

DATE March 13, 1981

NAME OF OWNER Harris, S.W. and C.D. Harris, Inc.

ADDRESS OF OWNER 1713 North Tryon Street, Charlotte, NC 28206

LOCATION OF LOT Mt. Holly - Huntersville,Road, Lot 2, Blck B

As determined under the Rules and Regulations promulgated by the Commission for Health Services, Division of Health Services, North Carolina Department of Human Resources, Raleigh, North Carolina, the soils on the lot described above were found to be unsuitable for the installation of an individual septic tank - soil absorption system, due to the following reason:

Soil Structure Massive

Soil Permeability Unsuitable

John R. Adkisson

John R. Adkisson, Environmentalist