W

Date Received 2/23

APT No. 5532

T. C. No. _____

Map Date _____

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER Rodgers (LAST) Jerome (FIRST) Whitney (MIDDLE)

2) ADDRESS OF OWNER 1322 Marble St ZIP 28204

3) PHONE NO. Home 399-0465 Office 374-2015


4) LOCATION OF PROPERTY Lindsay Lane (STREET OR COUNTY ROAD)

5) SUBDIVISION Idlewild Acres LOT NO. 7 & 8 BLOCK NO. 1

MAP BOOK NO 1699 PAGE NO 473

6) DEED REFERENCE DEED BOOK 1752 PAGE NO 363

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

OWNER Jerome Whitney Rodgers

FORM NO. E-1-11-1-70

HEALTH DEPARTMENT'S COPY

Date Received 3/18/76

APT No. 5532

T. C. No.

Map Date

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER Rodgers (LAST) Jerome (FIRST) M. (MIDDLE)

2) ADDRESS OF OWNER 1322 Marble St. ZIP 28206

3) PHONE NO. Home 399-0665 Office 374-2015


4) LOCATION OF PROPERTY Lindsay Lane (STREET OR COUNTY ROAD)

5) SUBDIVISION Idlewild Acres LOT NO. 7 & 8 BLOCK NO. 1

MAP BOOK NO. 1698 PAGE NO. 473

6) DEED REFERENCE DEED BOOK 2907 PAGE NO. 489

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

OWNER Jerome M. Rodgers

FORM NO. E1-11-3M-6-75

HEALTH DEPARTMENT'S COPY

SOIL INVESTIGATION REPORT

Date of Investigation 3/17/76 APT NO. 5532

Owner J. W. Rodgers

Location of Property Lot No. 7 & 8, Blk 1 Lindsay Ln.
TCN: 193-051-07 and 08

Soil Suitability Ratings

Soil Properties	Soil 1	Soil 2	Soil 3	Soil 4
1. Soil Series	Wilkes	Enon		
2. Soil Slope	Acceptable 2-8%	Acceptable 2-4%		
3. Soil Depth	Unacceptable <20"	Unacceptable <36"		
4. Soil Texture	Unacceptable silt clay	Unacceptable silt clay		
5. Soil Structure	Unacceptable massive	Unacceptable massive		
6. Restrictive Horizons	—	—		
7. Soil Drainage	Acceptable W.T. >48"	Acceptable W.T. >48"		
8. Soil Permeability (Percolation Rate)	Unacceptable >120 min/in	Unacceptable >120 min/in		
9. Other	—	—		
10. Overall Rating	Unacceptable	Unacceptable		


Recommendations Lot not recommended for installation of a septic tank system

See diagram on back

W. Everette Rogers, Jr.
Soil Scientist

3/18/75
HHD 539

DIAGRAM OF PROPERTY



3/18/75

EMD 539

MECKLENBURG COUNTY
Department of Public Health
1200 Blythe Boulevard
Charlotte, North Carolina 28208

DATE ISSUED
1. 3/24/76
2. _____
3. _____

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

SIR NO. 5532
T.C. NO. 193-051-07 & 08
MAP DATE -

NAME OF OWNER Rodgers, Jerome W.

ADDRESS OF OWNER 1322 Marble Street, Charlotte, N. C. 28208

LOCATION OF LOT Lindsay Lane, Lot 7 & 8, Block 1

The lot described above is not recommended for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge due to the following:

Unsuitable soil

Slow Permeability and percolation rate

However, a building permit may be issued upon executing the enclosed forms. The forms must then be notorized and recorded with the Register of Deeds Office, which is located in the County Office Building.

John R. Adkisson

John R. Adkisson, Environmentalist
On Premises Waste Disposal Branch
Environmental Health Department

JRA:jjk
(Stencil No.)
EHD 359
8/74

FORM NO.
E-19-8-21-74