Date Received 6/20/79

RECEIVED
JUN 19 1979
ENVIRONMENTAL HEALTH

APT No. 15812
T. C. No. 109-313-05
Map Date 4/4/79

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Rogers (LAST) Mr. and Mrs. Harry (FIRST) L. (MIDDLE)

2) ADDRESS OF OWNER 937 Hickory Nut St. ZIP 28205

3) PHONE NO. Home 333-5979 Office same


4) LOCATION OF PROPERTY Brickstone Drive (Clear Creek Township)
STREET OR COUNTY ROAD

5) SUBDIVISION Sunset Hills LOT NO. 76 and 77 BLOCK NO.

MAP BOOK NO 6 PAGE NO. 593

6) DEED REFERENCE DEED BOOK 1668 PAGE NO 525

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

Harry B Rogers & wife
OWNER
Andrew J. Rogers

EHD-5-76

Environmental Health Department's Copy

NORTH CAROLINA
DEPARTMENT OF HUMAN RESOURCES
DIVISION OF HEALTH SERVICES
RALEIGH, NORTH CAROLINA

APPENDIX H
SITE EVALUATION

APT 15812

(Ground Absorption Sewage Disposal)

OWNER: Mr. & Mrs. Harry B. Rogers
ADDRESS: 237 Hickory Nut Dr.
COUNTY: Charlotte 28205
LOCATION OF SITE: Brickstone Drive

DATE REQUESTED:
PLAT NO.: 109-313-05 Lots 76 77
LOT SIZE: 32,500

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	(S) 2-10% PS U	S complex PS slopes (U)	S PS U	S PS U +
2. SOIL TEXTURE (12-36 in.) (Sandy, loamy, clayey, Note 2:1, Clay)	S (PS) Clay U	S (PS) clay U	S PS U	S PS U
3. SOIL STRUCTURE (12.36 in.) (Clayey Soils)	S (PS) Blocky U	S (PS) Blocky U	S PS U	S PS U
4. SOIL DEPTH (In.)	(S) 48" PS U	S Depth PS Variable (U)	S PS U	S PS U
5. RESTRICTIVE HORIZONS (In.) (Impervious Strata, Rock)	(S) None PS U	(S) None PS U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (External & Internal)	(S) 76" ground water PS U	S Eroded Areas PS Channel (U) water	S PS U	S PS U
7. SOIL PERMEABILITY (Percolation Rate)	S (PS) Moderate U	S (PS) Moderate U	S PS U	S PS U
8. OTHER (Specify)	S Very Critical PS Area (U)	S PS U	S PS U	S PS U
9. SITE CLASSIFICATION	unsuitable	unsuitable		
SOIL SERIES	Cecil	Eroded Areas		

S - Suitable PS - Provisionally Suitable U - Unsuitable

* See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slope patterns, etc)


Recommendations/Comments:

Described By: William A. Martin

Title: Soil Scientist Date: 7-11-79

DHS Form 2604 (2/77)
Sanitation

2


Eroded Areas
325'
100'
100'
325'
Cecil
2-10%
Brick stone

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

SIR. NO. 15[illegible]
T.C. NO. 100-313-05
MAP DATE 4/4/79
DATE 7/11/79

NAME OF OWNER Mr. and Mrs. Harry B. Rogers

ADDRESS OF OWNER 937 Hickory Nut Street Charlotte, NC 28205

LOCATION OF LOT Brickstone Drive Sunset Hills Subdivision Lots 76 and 77

As determined under the Rules and Regulations promulgated by the Commission for Health Services, Division of Health Services, North Carolina Department of Human Resources, Raleigh, North Carolina, the soils on the lot described above were found to be unsuitable for the installation of an individual septic tank - soil absorption system. [redacted]

Very limited area of provisionally suitable soil.
Please submit plot of proposed building and septic tank system location.

John R. Adkisson

John R. Adkisson, Environmentalist