374-2113

Date Received 2/5/79

APT No. 15087

T. C. No. [redacted]

Map Date _____

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Giambalvo (LAST) Charles (FIRST) M. (MIDDLE)

2) ADDRESS OF OWNER c/o Wellworth Realty Co.Rt.1,Box 390,Davidson,N.C ZIP 28036

3) PHONE NO Home _____ Office 333-4957


4) LOCATION OF PROPERTY River Circle (STREET OR COUNTY ROAD)

5) SUBDIVISION Riverview Extension LOT NO 10 BLOCK NO K

MAP BOOK NO 9 PAGE NO 57

6) DEED REFERENCE DEED BOOK 3726 PAGE NO 184

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on-site inspection of the lot hereinafter described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface soil absorption effluent discharge.



7) ACCURATELY DIAGRAM & DIMENSION LOT

Charles Giambalvo
OWNER

EHD-5-76

Environmental Health Department's Copy

NORTH CAROLINA
DEPARTMENT OF HUMAN RESOURCES
DIVISION OF HEALTH SERVICES
RALEIGH, NORTH CAROLINA

APPENDIX H
SITE EVALUATION
(Ground Absorption Sewage Disposal)

S.I.R. No. 15087
TC 023-085-20
Lot 10 Block A

OWNER: Charles M. Giambalvo
ADDRESS: Foxcroft Subdivision - R-1 Box 390
COUNTY: Mecklenburg, Davidson, N.C. 28036
LOCATION OF SITE: River Circle

DATE REQUESTED: 2-5-79
PLAT NO.:
LOT SIZE: 19588

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	S PS 10-30 (U)	S PS U	S PS U	S PS U
2. SOIL TEXTURE (12-36 in.) (Sandy, loamy, clayey, Note 2:1, Clay)	S PS 2-1 clay (U)	S PS U	S PS U	S PS U
3. SOIL STRUCTURE (12-36 in.) (Clayey Soils) ✓	S PS Massive (U)	S PS U	S PS U	S PS U
4. SOIL DEPTH (In.)	S PS <48" (U)	S PS U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (In.) (Impervious Strata, Rock)	S Rock + clay PS <48" (U)	S PS U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (External & Internal)	S PS slow (U)	S PS U	S PS U	S PS U
7. SOIL PERMEABILITY (Percolation Rate) ✓	S PS slow (U)	S PS U	S PS U	S PS U
8. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U
9. SITE CLASSIFICATION ✓	Unsuitable			
SOIL SERIES	Helena Enon complex			

S - Suitable PS - Provisionally Suitable U - Unsuitable


* See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slope patterns)

Recommendations/Comments:

Described By: William B. Ramsey
Title: Soil Scientist
Date: 2-7-79

dhs form 2601 (1/79)
Sanitation

2



Lot # 10 Block K

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE NORTH CAROLINA 28203

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

SIR.NO. 15087
T.C. NO. 023-005-20
MAP DATE
DATE Feb. 7, 1979

NAME OF OWNER Giambalvo, Charles M.

ADDRESS OF OWNER c/o Wellworth REalty Co., DAvidson, N.C.

LOCATION OF LOT River Circle, Riverview Ext., Lot 10, Block K

As determined under the Rules and Regulations promulgated by the Commission for Health Services, Division of Health Services, North Carolina Department of Human Resources, Raleigh, North Carolina, the soils on the lot described above were found to be unsuitable for the installation of an individual septic tank-soil absorption system. This site cannot be approved for a septic tank system due to the following reason:

Soil Structure Massive
Soil Permeability Unsuitable
Site Classification Unsuitable

Stephen J. Wood, Environmentalist

EHD 398
7/77

R