Date Received 10/24/79

APT No 16267

T. C. No 108-083-10

Map Date 5/23/78

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Brumbl (LAST) William (FIRST) Bruce (MIDDLE)

2) ADDRESS OF OWNER 2115 Suburnum ave ZIP 28205

3) PHONE NO Home 377-1456 Office


4) LOCATION OF PROPERTY Myra Way (STREET OR COUNTY ROAD)

5) SUBDIVISION Hutchison LOT NO 47 BLOCK NO.

MAP BOOK NO 7 PAGE NO 695

6) DEED REFERENCE DEED BOOK 3111 PAGE NO 155.

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface soil absorption effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

W. B. Brumble.
OWNER

EHD-5-76

Environmental Health Department's Copy

NORTH CAROLINA
DEPARTMENT OF HUMAN RESOURCES
DIVISION OF HEALTH SERVICES
REGION: NORTH CAROLINA

APPENDIX II
SITE EVALUATION

S. I. R. NO. 16267
T. C. # 108-083-10

(Ground Absorption Sewage Disposal)

OWNER William B. BRUSTLE
ADDRESS 215 LABURNUM AVE
COUNTY CHARLOTTE
LOCATION OF SITE MYRA Way LOT 47

DATE INSPECTED 10-24-79
PLAT NO.
LOT SIZE 20,000

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	S PS 2-10 U	S PS U	S PS U	S PS U
2. SOIL TEXTURE (12-36 in.) (Sandy loamy clayey, Note 2:1 Clay)	S PS 2:1 clay Saprolite U	S PS U	S PS U	S PS U
3. SOIL STRUCTURE (12-36 in.) (Clayey Soils)	S PS MASSIVE U	S PS U	S PS U	S PS U
4. SOIL DEPTH (In.)	S PS 48 U	S PS U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (In.) (Impervious Strata Rock)	S PS Saprolite U	S PS U	S PS U	S PS U
6. SOIL DRAINAGE/CONDITION (External & Internal)	S PS Slow U	S PS U	S PS U	S PS U
7. SOIL PERMEABILITY (Percolation Rate)	S PS SLOW U	S PS U	S PS U	S PS U
8. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U
9. SITE CLASSIFICATION	Unsuitable			

SOIL SERIES Wilkes

S - Suitable PS - Provisionally Suitable U - Unsuitable


* See Diagram on Back (Include Soil areas, property lines, roads, streams, gullies, rock areas, fill areas, wells, water bodies, slope patterns, etc.)

Recommendations/Comments

Described By: W. B. Ramsey
Title: Soil Scientist Date: 10-31-79

DHS Form 2691
Sanitation
EHD 538 (3/79)

3


LOT 47
MYRA WAY
HWY 89
200
WILL TAKE 2-10 C SLOPES
100

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

S.I.R. # 16267

T.C. # 108-083-10

DATE November 2, 1979

NAME OF OWNER Brumble, William R.

ADDRESS OF OWNER 2115 Laburnum Ave., Charlotte, NC 28205

LOCATION OF LOT Myra Way, Lot 47

As determined under the Rules and Regulations promulgated by the Commission for Health Services, Division of Health Services, North Carolina Department of Human Resources, Raleigh, North Carolina, the soils on the lot described above were found to be unsuitable for the installation of an individual septic tank - soil absorption system, due to the following reason:

Soil Structure Massive
Soil Permeability Unsuitable

John R. Adkisson

John R. Adkisson, Environmentalist