Date Received 7/12/77

APT No. 1283C

T. C. No. PC 135-3

Map Date

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER Bob McLEMORE & CO, INC
(LAST) (FIRST) (MIDDLE)

2) ADDRESS OF OWNER P.O. Box 25746 CHARLOTTE, N.C. ZIP 28212

3) PHONE NO. Home _____ Office 545-6111


4) LOCATION OF PROPERTY TIMBER RIDGE DR
(STREET OR COUNTY ROAD)

5) SUBDIVISION FARMWOOD #8 LOT NO 20 BLOCK NO. J

MAP BOOK NO _____ PAGE NO. _____

6) DEED REFERENCE DEED BOOK _____ PAGE NO _____

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

Peter L Lockel Asst. V.P.
OWNER

FORM NO E1-11-3M-6-75

HEALTH DEPARTMENT'S COPY

Apt 12830

DEPARTMENT OF HUMAN RESOURCES
DIVISION OF HEALTH SERVICES

APPENDIX I

SITE EVALUATION

(Ground Absorption Sewage Disposal)

Name: Bon Maison & Co Inc. Date Received: July 6, 1977

Address: Box 25746 Charlotte Plat No. —

County: Mecklenburg Lot Size: 66 acres by 11.

Location of Site: Timber Ridge Dr. Lot No. 20 & Tract 1

Existing use: RT-35-01

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. [illegible]	S PS U —	S PS U	S PS U	S PS U
2. [illegible] (12-36 in.) [illegible], loamy, clayey, [illegible])	S PS U —	S PS U	S PS U	S PS U
3. SOIL STRUCTURE (12-36 in.) [illegible] soils)	S PS U —	S PS U	S PS U	S PS U
4. [illegible] DEPTH (In.)	S PS U —	S PS U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (In.) (Impervious Strata, rock)	S PS U —	S PS U	S PS U	S PS U
6. SOIL DRAINAGE (GROUNDWATER (External & Internal)	S PS U poorly drained	S PS U	S PS U	S PS U
7. SOIL PERMEABILITY (Percolation Rate)	S PS U [illegible]	S PS U	S PS U	S PS U
8. OTHER (Specify)	S PS U [illegible]	S PS U	S PS U	S PS U
9. SITE CLASSIFICATION*	Unsuitable			
SOIL SERIES	Chewacla			

S - Suitable PS - Provisionally Suitable U - Unsuitable


* See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slope pattern, etc.)

Recommendations/Comments: Based on this investigation, the lot was found to have soils generally unsuitable for installation of a septic tank system.

Described By: W. Edmund Cornwell

Title: Soil Scientist Date: July 11, 1977

DHS Form 2601 (2/77)
Sanitation


158'
Bass Pond Rd.
342'
314'
Chevrolet
243'
Timber Ridge Dr.

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

DATE ISSUED
1. 7-13-77
2. _____
3. _____

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

SIP NO. 12830
T.C. NO. P.O.135-351-01
MAP DATE _____

NAME OF OWNER: **Bob McLemore & Company, Inc.**

ADDRESS OF OWNER: **P.O. Box 25746, Charlotte, NC 28212**

LOCATION OF LOT: **Timber Ridge Drive, Lot 20, Block J**

The lot described above is not recommended for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge due to the following:

Soil Permeability Unsuitable.

Area subject to flooding.

John R. Adkisson
John R. Adkisson, Environmentalist
On Premises Waste Disposal Section

JRA:glr

(Stencil No.)
ENV 398
8/74

FORM NO.
E-19-8-21-74

A