MECKLENBURG COUNTY HEALTH DEPARTMENT
SITE EVALUATION REPORT
SERIAL NUMBER 16683

File: 7030A Action 2

Parcel: PO 139-151-03 ☒ PC

Location: Millview Trace Lane

Subdivision:


Lot: 34 Block: 2 Acres: .84

Owner:
Address:

Comments: 100% Repair

Described by: William R. Marlin

Date: 9-10-90



***** EVALUATION KEY *****

S = Suitable U = Unsuitable
PS = Provisionally Suitable
The "Area Classification" below indicates the suitability of areas in the diagram.

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4	AREA 5	AREA 6
Topography	(S) PS U 6-12%	S PS (U) complex slopes	(S) PS U 6-12%	(S) PS U 2-8%	S PS (U) Depression	S PS U —
Texture	S (PS) U clay	S PS U —	S (PS) U clay	S PS (U) some 2:1 clay	S PS U —	S PS U —
Structure	S (PS) U Blocky	S PS U —	S (PS) U Blocky	S (PS) U Blocky	S — PS U	S PS U —
Drainage	S (PS) U >36" water	S PS U —	S (PS) U 36" to water	S PS (U) some perched water 30-36"	S PS U —	S PS U —
Depth	S (PS) U 36-38"	S PS U —	S PS (U) 32-36"	S (PS) U 36"+	S PS U —	S PS U —
Restrictive Horizons	S (PS) U >36"	S PS U —	S (PS) U 36"	S (PS) U 36"	S PS U —	S PS U —
Available Space	S PS (U) Restricted	S PS U	S PS (U) Restricted	S PS U	S PS U	S PS U —
Other (specify)	S PS U	S PS U	S PS U	S PS U	S PS U	S PS (U) Fill
Soil Group/Series	IV Cecil-Lilly	complex slopes	IV Appling-Lilly	Helena-Lilly	Depression	Fill
Area Classification	S PS (U)	S PS (U)	S PS (U)	S PS (U)	S PS (U)	S PS (U)