

1324 JOHN KIRK DR

5/30/2007

duponbj

Groundwater and Wastewater Services File Imaging Project
May 2007
Barcode Font = IDAutomationHC39M

APPLICATION FOR SOIL INVESTIGATION

MECKLENBURG COUNTY
HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH DIVISION
PAID
OCT 25 1988

MECKLENBURG COUNTY ENVIRONMENTAL HEALTH

1200 BLYTHE BOULEVARD
CHARLOTTE, NC 28203
PHONE (704) 374-4603

(OFFICE USE ONLY)

FILE: 5140A

TC: _____

☐ PC ☐ REPT

JOB LOCATION

① ADDRESS: 1324 East Malland Creek Church Rd Charlotte, NC 28213

② SUBDIVISION: _____ ③ LOT: _____ ④ BLOCK: _____

⑤ PARCEL REFERENCE: BOOK NO.: 049-321-62 PO PAGE NO.: _____ PARCEL NO.: _____

⑥ DEED REFERENCE: BOOK NO.: _____ PAGE NO.: _____

OWNER


⑦ NAME: James (FIRST) William (MIDDLE) Kirk (LAST)

⑧ MAILING ADDRESS: 1224 East Malland Creek Church Rd

⑨ CITY: Charlotte ⑩ STATE: NC ⑪ ZIP: 28213

⑫ PHONE: (WORK) _____ (HOME) 549-0876

⑬ Accurately diagram and dimension lot.



⑭ The undersigned, owner of the property described above as the "JOB LOCATION" has read the foregoing application, acknowledges that the contents of same are true, and authorizes agents of the MECKLENBURG COUNTY DEPARTMENT OF ENVIRONMENTAL HEALTH to enter onto the property for the purpose of processing this request.

Signed: James William Kirk

Date: 10-25-88

Mecklenburg County services are available without regard to ethnic origin, sex, or disability.

WHITE - ENVIRONMENTAL HEALTH DEPARTMENT'S COPY ● CANARY - ENVIRONMENTALIST'S COPY ● PINK - OWNER'S COPY

MECKLENBURG COUNTY HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH DIVISION

CHARGE SLIP

Date 10/25/88

Name/Company James W. Kirk

Sanitation _____

Vector Control _____

O.P.W.D. ✓

Service: soil investigation
1324 E. Wilkinson Blvd.

MECKLENBURG COUNTY
HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH DIVISION
PAID

OCT 25 1988

Fee: $30.00

ck #5499

Completed by _____ Collected by _____

TO: ENVIRONMENTAL HEALTH DEPT.
BUILDING STANDARDS DEPT.
DEPT. OF ENVIRONMENTAL PROTECTION/
SOLID AND HAZARDOUS WASTE

DATE 7/6/88

FROM: COUNTY ENGINEERING DEPARTMENT

EHD FILE _____ JURISDICTION CODE Meck

PARCEL NUMBER 049-321-02p0

ASSIGNED ADDRESS 1324 Mallard Creek Church Rd

EXISTING ADDRESS _____

PROJECT NAME N/A

THE ABOVE DESCRIBED LOCATION HAS BEEN CHECKED CONCERNING:

	APPROVED	DISAPPROVED
1. SUBDIVISION REGULATIONS	/ /	/ /*
2. FLOODWAY REGULATIONS	/ /	/ /*
3. EROSION CONTROL REGULATIONS	/ /	/ /*
4. PUBLIC UTILITY EASEMENT	/ /	/ /*

	PRESENT	NOT PRESENT
5. PUBLIC UTILITY EASEMENT	/ /*	/ ✓
6. PROPERTY FRONTS ON THOROUGHFARE	/ ✓ /*	/ /
7. DRIVEWAY PERMIT REQUIRED	/ /*	/ ✓

*If checked, further investigation will be required to determine whether a building permit can be issued by Building Standards for the site.

REMARKS: Septic Tank

NOTE: THIS FORM MUST BE TURNED IN AT THE CASHIER'S OFFICE AT BUILDING STANDARDS WHEN PAYING PERMIT FEES.
A CERTIFICATE OF OCCUPANCY WILL NOT BE GRANTED UNTIL THE TRANSPORTATION DIVISION GRANTS FINAL APPROVAL ON DRIVEWAY(S).

SIGNED: Dezi

OPWEAR 06-88

NEW ADDRESS / /*

FORM 100

Mecklenburg County
Health Department

Basil G. Delta, M.D., M.P.H.
Health Director

October 31st, 1988

James William Kirk
1223 E. Mallard Creek Church Road
Charlotte, NC 28213

RE: Property located at E. Mallard Creek Church Road
FILE: 5140A
PARCEL: 04932102 PO

Dear Sir:

At your request a soils investigation was conducted on the property designated above. Results of this investigation showed the site to be classified as UNSUITABLE under criteria as set forth in Section .1900 of the North Carolina Administrative Code, Title 10, Department of Human Resources, Chapter 10, Division of Health Services; Sanitary Engineering Section, Subchapter 10A, Sanitation. A copy of the Site Evaluation Report (Serial Number 11914) is enclosed.

The soil on this property is not suitable for use with any conventional, modified or alternative system of which I am aware.

If I can be of assistance, please do not hesitate to call.

Very truly yours,

Sylvia D. Daniel, R.S., Supervisor
On Premises Waste Disposal & Water Supply

Enclosure

Environmental Health Division
1200 Blythe Boulevard • Charlotte, North Carolina 28203 • (704) 376-4603

MECKLENBURG COUNTY ENVIRONMENTAL HEALTH
SITE EVALUATION REPORT
SERIAL NUMBER

File: 5140A Action 3

Parcel: 049-321-07 ☐ PC

Location: E. Mallard Creek Church Road

Subdivision:


Lot: Block: Acres: Approx 1.0

Owner: James William Kirk
Address: 1224 E. Mallard Creek Church Road
Charlotte, N. C. 28213

Comments: _____

Described by: William R. Marks

Date: 10-27-88



***** EVALUATION KEY *****

S = Suitable U = Unsuitable
PS = Provisionally Suitable
The "Area Classification" below indicates the suitability of areas in the diagram.

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4	AREA 5	AREA 6
Topography	(S) PS U 2-10%	S PS U —	S PS U	S PS U	S PS U	S PS U
Texture	S PS (U) 2-1C clay	S PS U —	S PS U	S PS U	S PS U	S PS U
Structure	S (PS) U Blocky	S PS (U) compacted	S PS U	S PS U	S PS U	S PS U
Drainage	S PS (U) perched water 6-12"	S PS U —	S PS U	S PS U	S PS U	S PS U
Depth	S PS (U) 18-36"	S PS U	S PS U	S PS U	S PS U	S PS U
Restrictive Horizons	S (PS) U 7-36"	S PS U	S PS U	S PS U	S PS U	S PS U
Available Space	S (PS) U	S PS U	S PS U	S PS U	S PS U	S PS U
Other (specify)	S PS U	S PS (U) Fill	S PS U	S PS U	S PS U	S PS U
Soil Group/Series	IVB Helena-Lilo	Fill / IVB Helena-Lilo				
Area Classification	S PS (U)	S PS (U)	S PS U	S PS U	S PS U	S PS U