Date Received _____

APT No. 12387

T. C. No. 047-066

Map Date _____

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Edds (LAST) [illegible] (FIRST) (MIDDLE)

2) ADDRESS OF OWNER 6209 Longwood Dr. ZIP 28213

3) PHONE NO Home 596-5766 Office 596-5601


4) LOCATION OF PROPERTY Longwood Dr. (STREET OR COUNTY ROAD)

5) SUBDIVISION Ridgeview Manes LOT NO 1 BLOCK NO 3

MAP BOOK NO 4844 PAGE NO 449

6) DEED REFERENCE DEED BOOK 2214 PAGE NO 509

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface soil absorption effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

Melvin Edds
OWNER

EHD-5.74

Environmental Health Department's Copy

Pink copy

Date Received

APT No. 12337

T. C. No. 047-06

Map Date

RECEIVED
MECK COUNTY DEPARTMENT OF
MAY 13 1977
ENVIRONMENTAL HEALTH

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER _____ (LAST) _____ (FIRST) _____ (MIDDLE)

2) ADDRESS OF OWNER _____ ZIP _____

3) PHONE NO Home _____ Office _____


4) LOCATION OF PROPERTY _____ (STREET OR COUNTY ROAD)

5) SUBDIVISION SIDEVIEW ACRES LOT NO 1 BLOCK NO 2

MAP BOOK NO 44 PAGE NO 419

6) DEED REFERENCE DEED BOOK 2111 PAGE NO 509


Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with surface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

OWNER

Environmental Health Department's Copy



SOIL INVESTIGATION REPORT

Date of Investigation _____ AFT NO. 12387

Owner _____

Location of Property _____

Soil Suitability Ratings

Soil Properties	Soil 1	Soil 2	Soil 3	Soil 4
1. Soil Series				
2. Soil Slope				
3. Soil Depth				
4. Soil Texture				
5. Soil Structure				
6. Restrictive Horizons				
7. Soil Drainage				
8. Soil Permeability (Percolation Rate)				
9. Other				
10. Overall Rating				

Recommendations _____

_____

_____


_____

_____

_____

3/75

DIAGRAM OF PROPERTY



3/18/75
EHD 539

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

DATE ISSUED
1. 6-6-78
2. _____
3. _____

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

SIP NO. 12387
T.C. NO. ~~067-086-08~~
M/P DATE _____

NAME OF OWNER **Edwards, Charles Melvin**

ADDRESS OF OWNER **6709 Brushwood Drive, Charlotte, NC 28213**

LOCATION OF LOT **Brushwood Drive, Lot 1, Block 3**

The lot described above is not recommended for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge due to the following:

Soil Permeability Unsuitable.

Percolation rate in excess of 200 min/in.

John R. Atkisson

John R. Adkisson, Environmentalist
On Premises Waste Disposal Section

JRA: glr

(Stencil No.)
EHD 359
8/74

FORM NO.
E-11-8-21-74

R