Date Received 4/22

MECK COUNTY DEPARTMENT OF
RECEIVED
APR 15 1977

APT No. 12266

T. C. No. 109.263-09

Map Date ———

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Midwood (LAST) Realstate (FIRST) Corp. (MIDDLE)

2) ADDRESS OF OWNER 2004 Belvedere Ave. Charlotte, NC ZIP 28205

3) PHONE NO. Home 3764501 Office


4) LOCATION OF PROPERTY ~~Wallingford~~ Norwich Rd (STREET OR COUNTY ROAD)

5) SUBDIVISION Marwood Acres LOT NO. 9 BLOCK NO. B

MAP BOOK NO 109 PAGE NO. 26

6) DEED REFERENCE: DEED BOOK 1623 PAGE NO. 344

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge.



7) ACCURATELY DIAGRAM & DIMENSION LOT

Florence R. Griffin
OWNER

EHD-5-76

Environmental Health Department's Copy

SOIL INVESTIGATION REPORT

Date of Investigation 4-24-77 APT NO. 12266

Owner Midwest Realtech Corp Tax no 263-88

Location of Property Norwich Rd

Soil Suitability Ratings

Soil Properties	Soil 1	Soil 2	Soil 3	Soil 4
1. Soil Series	Mac Hlenberg	Iredell		
2. Soil Slope	Suitable 2-6%	Suitable 2-6%		
3. Soil Depth	Suitable 48"	unsuitable < 36"		
4. Soil Texture	unsuitable 2-1 Expandy clay	unsuitable 2-1 Expandin clay		
5. Soil Structure	unsuitable Massive	unsuitable Massive		
6. Restrictive Horizons				
7. Soil Drainage	Suitable water Table >6'	unsuitable perched high water Table		
8. Soil Permeability (Percolation Rate)	unsuitable slow >20 min/in	unsuitable v. slow >20 min/in		
9. Other				
10. Overall Rating	unsuitable	unsuitable		


Remarks Recommendations Based on the investigation, the soils on the lot were found to be unsuitable for installation of a septic tank system.

See Hagerstown Soils

William R. Maslin

WRM

3/10/75


150'
Norwith Rd
Mecklenburg
162'
260'
Tisdell
148'

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

DATE ISSUED
1. 4-28-77
2. _____
3. _____

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

SIR NO. 12266
T.C. NO. 109-263-09
MAP DATE _____

NAME OF OWNER Midwood Realestate Corporation

ADDRESS OF OWNER 2004 Belvedere Ave, Charlotte, NC 28205

LOCATION OF LOT Norwich Road, Lot Q, Block B

The lot described above is not recommended for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge due to the following:

Soil Permeability Unsuitable

Percolation rate in excess of 200 min/in.

John R. Adkisson, Environmentalist
On Premises Waste Disposal Section

JRA: glr

(Stencil No.)
EHD 389
8/74

FORM NO.
T-1-8-21-74