Date Received 7/12/77

APT No. 12841

T. C. No. 141 055 46

Map Date

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Kahala Corp.
(LAST / FIRST / MIDDLE)

2) ADDRESS OF OWNER P.O. Box 17576, Charlotte, N.C. ZIP 28211

3) PHONE NO Home ____ Office 366 2585


4) LOCATION OF PROPERTY Timberley Place
(STREET OR COUNTY ROAD)

5) SUBDIVISION ____ LOT NO 10 BLOCK NO. ____

MAP BOOK NO 10 PAGE NO 37

6) DEED REFERENCE DEED BOOK ____ PAGE NO ____

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

H. W. Martin, Secy.
OWNER

EHD-5-76

Environmental Health Department's Copy

NORTH CAROLINA
DEPARTMENT OF HUMAN RESOURCES
DIVISION OF HEALTH SERVICES
RALEIGH, NORTH CAROLINA

APPENDIX H
SITE EVALUATION

(Ground Absorption Sewage Disposal)

APT 12841
72 141 155-41
Lot 5

OWNER: Pollard Corp
ADDRESS: Rt 1 Box 1757
COUNTY: Charlotte N.C.
LOCATION OF SITE: Timberly Class

DATE REQUESTED: 7-12-77
PLAT NO.:
LOT SIZE: 43,560

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	(S) PS 6-15% U	S PS — U	S PS U	S PS U +
2. SOIL TEXTURE (12-36 in.) (Sandy, loamy, clayey, Note 2:1, Clay)	S (PS) clay U	S PS — U	S PS U	S PS U
3. SOIL STRUCTURE (12.36 in.) (Clayey Soils)	S (PS) 3c-Ky U	S PS — U	S PS U	S PS U
4. SOIL DEPTH (In.)	S Saprolite PS @ 24" (U)	S PS — U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (In. (Inprevious Strata, Rock)	S PS — U	S PS — U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (External & Internal)	(S) To Fair PS water U Table	S Seasonal PS perched (U) water Table	S PS U	S PS U
7. SOIL PERMEABILITY (Percolation Rate)	S Slow PS Fair (U) Poor	S Subject PS To flood. (U)	S PS U	S PS U
8. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U
9. SITE CLASSIFICATION	unsuitable	unsuitable		
SOIL SERIES	Pacolet w. Mas	Chewacla		

S - Suitable PS - Provisionally Suitable U - Unsuitable


* See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slope patterns, etc)

Recommendations/Comments: Based on the investigation, site is not considered to be suitable for the installation of a septic tank system

Described By: William C. Marlin

Title: Soil Scientist Date: 7-20-77

DHS Form 2601 (2/77)
Sanitation


#
15'
Chevrolet
16'2
Porch
Walks
3'1"
e 3'
Timberly Place

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE NORTH CAROLINA 28203

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

SIR. NO. 12841
T.C. NO. 141-055-46
MAP DATE
DATE 7-27-77

NAME OF OWNER **Kahala Corporation**

ADDRESS OF OWNER **P.O. Box 17576, Charlotte, NC 28211**

LOCATION OF LOT **TImberley Place, Lot 10**

As determined under the Rules and Regulations of the North Carolina Department of Human Resources, Division of Health Services, Raleigh, North Carolina, the soils on the lot described above were found to be unsuitable for the installation of an individual septic tank-soil absorption system. This site cannot be approved for a septic tank system due to the following reason:

Soil Depth Unstuiable.

Soil Permeability Unsuitable.

John R. Adkisson, Evnironmentaliet
On Premises Waste Disposal Section

JRA:glr

EHD 398
7/77

R