MECKLENBURG COUNTY HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH
DIVISION

"INDIVIDUAL SEPTIC TANK SYSTEMS"

RECORDED IN NUMERICAL ORDER
BY FILES

Date Received 9/31/11

APT No. 1151

T. C. No. 39.192.01

Map Date 3-96

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Lanier (LAST) Jack (FIRST) C (MIDDLE)

2) ADDRESS OF OWNER 2101 Oakdale Rd ZIP 28216

3) PHONE NO. Home 392 4778 Office


4) LOCATION OF PROPERTY Northcliff Dr. (STREET OR COUNTY ROAD)

5) SUBDIVISION Cedargrove Park LOT NO. 10 BLOCK NO. 1

MAP BOOK NO. PAGE NO.

6) DEED REFERENCE. DEED BOOK 2518 PAGE NO. 469

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

OWNER

EHD-5-76

Environmental Health Department's Copy

SOIL INVESTIGATION REPORT

Date of Investigation April 5, 1977 APT NO. 12151

Owner Jack L. Jarvis P.O. 337-17201

Location of Property Northcliff Dr. Lots 21 K

Soil Suitability Ratings

Soil Properties	Soil 1	Soil 2	Soil 3	Soil 4
1. Soil Series	Cheswold	Ingleside		
2. Soil Slope	—	suitable 2-8%		
3. Soil Depth	—	unsuitable <40"		
4. Soil Texture	—	unsuitable 2:1 Expanding clay		
5. Soil Structure	—	unsuitable massive		
6. Restrictive Horizons	—	—		
7. Soil Drainage	unsuitable poorly drained	unsuitable perched high water Table		
8. Soil Permeability (Percolation Rate)	unsuitable seasonal high water table 18" from surface subject to flooding	unsuitable slow-very slow percolation		
9. Other				
10. Overall Rating	unsuitable	unsuitable		

Remarks; Recommendations: Based on this investigation, the soils on the lot were found to be predominately unsuitable for installation of a septic tank system.


See diagram on back

William A. Marks
Soil Scientist

WEC

3/18/75
EHE 539

DIAGRAM OF PROPERTY



3/18/75

339

[redacted] COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

DATE ISSUED
1. ~~4/14/77~~
2. _____
3. _____

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

SIP NO. 12151
T.C. NO. ~~P.O. 038-102~~-01
MAP DATE ~~3-8-76~~

NAME OF OWNER: Lanier, Jack E.

ADDRESS OF OWNER: 2101 Oakdale Road, Charlotte, N. C. 28216

LOCATION OF LOT: Northcliff Drive, Lot 10, Blk 1

The lot described above is not recommended for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge due to the following:

Soil permeability unsuitable

Percolation rate in excess of 200Min./in.

John R. Adkisson

John R. Adkisson, Environmentalist
On Premises Waste Disposal Section

JRA:jjk

(Stencil No.)
EHD 359
8/74

FORM NO.
E-11-8-21-74

Date Received 3/31/77 RECEIVED

MAR 24 1977

ENVIRONMENTAL HEALTH

T. C. No. 24-

Map Date

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Howard Mance Company
(LAST / FIRST / MIDDLE)

2) ADDRESS OF OWNER 420 Hawthorne Lane, Charlotte, N. C. ZIP 28204

3) PHONE NO. Home _____ Office _____

4) LOCATION OF PROPERTY Rea Road
(STREET OR COUNTY ROAD)


5) SUBDIVISION _____ LOT NO _____ BLOCK NO. _____

MAP BOOK NO 1989 PAGE NO. 602

6) DEED REFERENCE: DEED BOOK 1989 PAGE NO. 602

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge

See attached survey.



7) ACCURATELY DIAGRAM & DIMENSION LOT

Howard Mance
OWNER

EHD-S-76

Environmental Health Department's Copy