Date Received 8-13-84

RECEIVED
AUG 13 1984
ENVIRONMENTAL HEALTH

SIR No. 213/2

T. C. No. Po 135-371-99

Map Date I

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER BOB MCLEMORE CO. INC.
(LAST FIRST MIDDLE)

2) ADDRESS OF OWNER PO BOX 25746 CHAR ZIP 28212

3) PHONE NO. Home ——— Office 545-6111


4) LOCATION OF PROPERTY 5739 FOWLER FARM ROAD
(STREET OR COUNTY ROAD)

5) SUBDIVISION FARMWOOD SEC #20 LOT NO. 18 BLOCK NO. W

MAP BOOK NO. 20 PAGE NO. 611

6) DEED REFERENCE: DEED BOOK _____ PAGE NO. _____

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge.



7) ACCURATELY DIAGRAM & DIMENSION LOT

BOB MCLEMORE CO INC
OWNER

8-8-84

EHD-5-76

Environmental Health Department's Copy

DEPARTMENT OF ENVIRONMENTAL HEALTH
MECKLENBURG COUNTY, NORTH CAROLINA

SITE EVALUATION

S.I.R. NO. 2312

T.C. NO. PO 135-391-91

(Ground Absorption Sewage Disposal)

OWNER: BOB McLEMORE CO. PLAT NO:
ADDRESS: PO Box 25746 LOT SIZE: 1.02
Charlotte 28212
LOCATION OF SITE: 5139 FOWLER FARM ROAD
Sect. 20

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	(PS) 2-4	(PS) 2-4	S PS U	S PS U
2. SOIL TEXTURE (12-36 inches) Sandy, Loamy, Clayey (Note 2-1 Clay)	(PS) Clayey-Loamy Mod Clay	(PS) Clayey	S PS U	S PS U
3. SOIL STRUCTURE (12-36 inches)	(PS) Blocky	(PS) Blocky	S PS U	S PS U
4. SOIL DEPTH (inches)	(PS) 12-24"	(PS) 22-24	S PS U	S PS U
5. RESTRICTIVE HORIZONS (Inches) (Impervious strata, Rock)	(PS) None	(PS) None	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (external and internal)	(PS) Slow (Flood Plain)	(PS) Adequate	S PS U	S PS U
7. OTHER (Specify)	S PS U	(PS) Inadequate Area	S PS U	S PS U
8. SOIL GROUP	IIa-tl	IIa		
9. SITE CLASSIFICATION	Unsuitable	Unsuitable		
10. SOIL SERIES	Flood Plain Drainageway (Mocksan)	Elodad Cecil		

S - Suitable PS - Provisionally Suitable U - Unsuitable

**See Diagram on Back (includes: soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slopes)

Recommendations/Comments:

Described by: Willard Ramsey
Title: Soil SCIENTIST

Date: 11-1-84

3d

Ditch
Colluvio
Material
1½' Depth
High Water
Table
1½'
Flood
Plain
Marsh
266
Ceda
Ponded
Area
Eroded
Colluvio
Area
1½-1½'
High Water
Table
125

MECKLENBURG COUNTY
Department of Environmental Health

November 5, 1984

Bob McLemore Company
P.O. Box 35746
Charlotte, NC 28212

Re: Property located at 5139 Fowler Farm Road, SIR 21312, TC PO 135-391-99

Dear Sir:

At your request a soils investigation was conducted on the property designated above. Results of this investigation showed the site to be classified as unsuitable under criteria as set forth in Section .1900 of the North Carolina Administrative Code, Title 10, Department of Human Resources, Chapter 10, Division of Health Services; Sanitary Engineering Section, Subchapter 10A, Sanitation.

The soil on this property is not suitable for use with any conventional system, modified or alternative, with which I am aware.

If I can be of assistance, please feel free to call.

Sincerely,

Bill D. Hardister, Jr.

Bill D. Hardister, Jr.
Environmental Health Supervisor

Enclosure