Date Received 7/12/77

APT No. 12828

T. C. No. P 6135

Map Date

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER BOB McLEMORE & Co, INC.
(LAST FIRST MIDDLE)

2) ADDRESS OF OWNER P.O. BOX 25746 CHAR N.C. ZIP 28212

3) PHONE NO. Home _____ Office 545-6111


4) LOCATION OF PROPERTY TIMBER RIDGE DR
(STREET OR COUNTY ROAD)

5) SUBDIVISION FARMWOOD #8 LOT NO 22 BLOCK NO J

MAP BOOK NO _____ PAGE NO _____

6) DEED REFERENCE DEED BOOK _____ PAGE NO _____

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

Patsy G Goebel
OWNER Bkr P.P.

FORM NO. E1-11-3M-6-75

HEALTH DEPARTMENT'S COPY

DEPARTMENT OF HUMAN RESOURCES
DIVISION OF HEALTH SERVICES

APPENDIX H
SITE EVALUATION

Apt. 12828

(Ground Absorption Waste Disposal)

Owner: Bob McLemore & Co, Inc. Date: July 12, 1977
Address: P.O. Box 25746 Charlotte Phone:
County: Mecklenburg Lot Size: 44,000 sq. ft.
Location of Site: Timber Ridge Subd. Lot no. 22 Blk 47
Soil Code No. 135-3[illegible]

FACTORS	AREA 1	AREA 2	AREA 3	AREA
[illegible]	S PS U —	S PS 3-6' U	S PS U	S PS U
[illegible] (12-36 in.) [illegible], clayey, [illegible])	S PS U —	S PS U Silty	S PS U	S PS U
[illegible] STRUCTURE (12-36 in.) [illegible] soils)	S PS U —	S PS U Massive	S PS U	S PS U
[illegible] WIDTH (In.)	S PS U —	S PS U 48+	S PS U	S PS U
[illegible] HORIZONS (In.) [illegible] Strata, rock)	S PS U —	S PS U —	S PS U	S PS U
[illegible] DRAINAGE, GROUNDWATER (External & Internal)	S PS U Poorly Drained	S PS U Perched high water table	S PS U	S PS U
[illegible] PERMEABILITY [illegible] Percolation Rate)	S PS U Seasonal high water table	S PS U 72 min/in	S PS U	S PS U
[illegible] (Specify)	S PS U floods	S PS U —	S PS U	S PS U
[illegible] CLASSIFICATION*	unsuitable	unsuitable		
[illegible]	Chewacla	Enon		


S - Suitable PS - Provisionally Suitable U - Unsuitable

[illegible] Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slope patterns, etc.)

[illegible] Recommendations/Comments: Based on this investigation the lot was found to have soils generally unsuitable for installation of septic tank systems.

Described By: W. Edward Crockett
Title: Soil Scientist Date: July 12, 1977

DHS Form 2601 (2/77)
Sanitation


50'
ENON
380-
332'
Chevelle
240-
Timber Ridge Dr.

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

DATE ISSUED
1. 7-13-77
2. _____
3. _____

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
MISS SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

SIP NO. 12828
T.C. NO. P.O.135-351-01
C/E DATE _____

NAME OF OWNER: Bob McLemore & Company, Inc.

ADDRESS OF OWNER: P.O. Box 25746, Charlotte, [redacted] 28212

LOCATION OF LOT: Timber Ridge Drive, Lot 22, Block J

The lot described above is not recommended for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge due to the following:

Soil Structure Massive

Soil Permeability Unsuitable.

John R. Adkisson

John R. Adkisson, Environmentalist
On Premises Waste Disposal Section

JRA:glr

(Stencil No.)
ENH 388
8/74

FORM NO.
E-19-8-21-74

R