Date Received 5-16-23

APT No. 6303

T. C No _____

Map Date _____

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER Waco Realty Company (LAST / FIRST / MIDDLE)

2) ADDRESS OF OWNER 1008 East Blvd. ZIP 28203

3) PHONE NO Home 334-1336 Office 333-8477


4) LOCATION OF PROPERTY Powell Street, Lot 54 White Forest (STREET OR COUNTY ROAD)

5) SUBDIVISION White Forest LOT NO 54 BLOCK NO. _____

MAP BOOK NO. 7 PAGE NO. 695

6) DEED REFERENCE: DEED BOOK 3544 PAGE NO. 237

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

MC Cocking
OWNER

FORM NO E-1-8-1-72

HEALTH DEPARTMENT'S COPY

MECKLENBURG COUNTY HEALTH DEPARTMENT
INTER-OFFICE COMMUNICATION

DATE: September 4, 1973

TO: Randy Reynolds
Environmentalist

FROM: W. Everette Lynn, Jr. W.E.L.
Soil Scientist

SUBJECT: APT #6303 (Waco Realty Co.)
Lot No. 54 on Powell Street
8-31-73

Soils were found to be of the Mecklenburg and Iredell series. These soils have very plastic and sticky clay subsoils which contain swelling clay minerals. The Iredell soils may have a perched high water table during periods of high rainfall. The area of Iredell on this particular lot occurs in a depressional area with a seasonal high water table. These factors result in inadequately slow percolation rate and permeability.

Based on these observations, the lot appears unsuitable for installation of a septic tank system.

MECKLENBURG COUNTY
Department of Public Health

1200 Blythe Boulevard
Charlotte, North Carolina 28203
Telephone 374-2113

Date Issued
1. ~~7~~
2. _____
3. _____

SDR No. ~~6333~~
T.C. No. ~~36-103~~ 05
8-7-73

SITE DISAPPROVAL REPORT
INDIVIDUAL SEPTIC TANK SYSTEM WITH SUBSURFACE, SOIL ABSORPTION, EFFLUENT DISCHARGE

NAME OF OWNER _____

ADDRESS OF OWNER _____ ZIP _____

LOCATION OF LOT _____

The lot described above has been disapproved for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge due to the following:

FAILURE TO PASS PERCOLATION TEST (60 minutes per inch or less)

	Test No.	Date of Test	Percolation Rate
~~X~~	1.	_____	_____ min/in
X	2.	8-14-73	130 min/in
_____	3.	_____	_____ min/in

_____ ON SITE INSPECTION REVEALED LOT TO BE UNSUITABLE FOR THE FOLLOWING REASON(S) _____

_____

_____

_____

R. M. Reynolds
Environmentalist

(Stencil No.)
EHD 398
8/70

FORM NO.
R-19-8-14-70

SEE INSTRUCTIONS ON BACK

Date Received 5-16-73

ICAR(S) Application No 6303

T C No

Map Date


MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

Application for an
Installation, Construction, Alteration, and/or Repair Permit
(Individual Septic Tank System with Subsurface, Soil Absorption, Effluent Discharge)

The owner of that property described hereinafter hereby applies to the Mecklenburg County Health Department for a permit to

1) ___ Install or Construct 2) ___ Alter or Repair an individual septic tank wastewater treatment system with a subsurface soil absorption, effluent discharge



3) PLOT PLAN (ACCURATELY DIMENSIONED)

4) No. of Bedrooms Three

5) Business (Type) May Not Employee ___

6) Washing Machine X Yes ___ No

7) Garbage Disposal X Yes ___ No

8) Dishwasher X Yes ___ No

9) Water Supply
A) Individual System X
B) Governmental System ___
C) Community System
1) Well source ___
2) Governmental source ___

10) Sewage System
House located within 200 feet of public sewer ___ Yes X No
House located within 200 feet of community sewer ___ Yes X No

11) FHA Case No ___

12) VA Case No ___

13) NAME OF OWNER Waco Realty Company (LAST / FIRST / MIDDLE)

14) ADDRESS OF OWNER 1008 East Blvd.

15) PHONE NO Home 334-1336 Office 333-8477

16) LOCATION OF SYSTEM Powell Street (STREET OR COUNTY ROAD)

17) SUBDIVISION White Forest Lot No. 54 Block No. ___

Map Book No. 7 Page No. 695

18) DEED REFERENCE — DEED BOOK 3544 AT PAGE 237

19) HAS A PERCOLATION TEST BEEN RUN? X YES ___ NO DATE RUN May, 1973

20) PTR NUMBER (See Instructions) ___

The undersigned person hereby agrees that he has read the foregoing application and that the contents of same are true. It is understood that any permit applied for herein shall be void and of no effect if any of the above facts are not true.

May 11, 1973
DATE OF APPLICATION

W. C. Cochran
OWNER

FORM NO E-4-9-1-72

HEALTH DEPARTMENT'S COPY

Date Received 2/16/76

APT No. 6303

T. C. No. 18 08305

Map Date 11/3/76

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Brumble (LAST) William (FIRST) Bruce (MIDDLE)

2) ADDRESS OF OWNER 2115 Fetherstone Circle ZIP 28215

3) PHONE NO. Home 377-1456 Office 535-6000


4) LOCATION OF PROPERTY Powell Rd (STREET OR COUNTY ROAD)

5) SUBDIVISION White Pines LOT NO. 54 BLOCK NO.

MAP BOOK NO 7 PAGE NO. 695

6) DEED REFERENCE DEED BOOK PAGE NO

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

Robinson Church Rd

OWNER W. B. Brumble, Jr.

EHD-5-76

Environmental Health Department's Copy

SOIL INVESTIGATION REPORT

Date of Investigation December 10, 1976 APT NO. 6303

Owner W. B. Brumble

Location of Property Powell Rd. lot no. 54 TCN 108-083.05

Soil Suitability Ratings

Soil Properties	Soil 1	Soil 2	Soil 3	Soil 4
1. Soil Series	Helena			
2. Soil Slope	unsuitable depression			
3. Soil Depth	suitable 48"+			
4. Soil Texture	unsuitable silt/expanding clay			
5. Soil Structure	unsuitable massive			
6. Restrictive Horizons	—			
7. Soil Drainage	unsuitable perched high water table			
8. Soil Permeability (Percolation Rate)	unsuitable very slow >200 min/in			
9. Other	—			
10. Overall Rating	unsuitable			


Recommendations Based on this investigation, the lot is not recommended for approval for installation of a septic tank system.

See diagram on back

W. Edward Cusamano
Soil Scientist

3/18/75
MD 539

DIAGRAM OF PROPERTY



3/18/75

339

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

DATE ISSUED
1. 12/15/76
2. _____
3. _____

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

SIP NO. 6303
T.C. NO. 108-083-05
MAP DATE 1-30-76

NAME OF OWNER Brumble, William Bruces

ADDRESS OF OWNER 2115 Laburnum Avenue, Charlotte, N. C. 28205

LOCATION OF LOT Powell Road, Lot 54, White Forest Subdivision

The lot described above is not recommended for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge due to the following:

Soil Permeability unsuitable

Percolation rate in excess of 200 min./in.

John R Adkisson

John R. Adkisson, Environmentalist
On Premises Waste Disposal Branch

JRA:jjk

(Stencil No.)
EHD 388
8/74

FORM NO.
I-11-8-21-74