Date Received 7/12/77

APT No. 12829

T. C. No. PC135-351-41

Map Date _____

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER BOB MCLEMORE & CO, INC
(LAST / FIRST / MIDDLE)

2) ADDRESS OF OWNER PO Box 25746 CHARLOTTE, N.C. ZIP 28212

3) PHONE NO Home _____ Office 545-6111


4) LOCATION OF PROPERTY TIMBER RIDGE DR.
(STREET OR COUNTY ROAD)

5) SUBDIVISION FARMWOOD #8 LOT NO 21 BLOCK NO. J

MAP BOOK NO _____ PAGE NO. _____

6) DEED REFERENCE DEED BOOK _____ PAGE NO _____

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

Peter L Gobel
OWNER Asst. V.P.

FORM NO ET-11-3M-6-75

HEALTH DEPARTMENT'S COPY

DEPARTMENT OF HUMAN RESOURCES
DIVISION OF HEALTH SERVICES

APPENDIX H
SITE EVALUATION

Apt. 12829

(Ground Absorption Sewage Disposal)

OWNER: Bob Peterson & Co., Inc. DATE REQUESTED: July 12, 1977
ADDRESS: P.O. Box 23746 Charlotte PLAT NO.: ——
COUNTY: Mecklenburg LOT SIZE: 46,000 sq ft
LOCATION OF SITE: Timber Ridge Rd. Lot No. 21 Block J
Soil Log No. PC 135-351-C1

FACTORS	AREA 1	AREA 2	AREA 3	
1. SLOPE (%)	S PS U ——	S PS U 3 E	S PS U	S PS U
2. SOIL TEXTURE (12-36 in.) (Sandy, loamy, clayey, organic clay)	S PS U ——	S PS U Appears to be	S PS U	S PS U
3. SOIL STRUCTURE (12-36 in.) (Blocky soils)	S PS U ——	S PS U Clays	S PS U	S PS U
4. DEPTH (In.)	S PS U ——	S PS U >48"	S PS U	S PS U
5. RESTRICTIVE HORIZONS (In.) (Bedrock, strata, rock)	S PS U ——	S PS U ——	S PS U	S PS U
6. SEASONAL GROUNDWATER (Surface & Internal)	S PS U Perch & Channel	S PS U Perched high water table	S PS U	S PS U
7. PERMEABILITY (Perc Rate)	S PS U Slow to moderate	S PS U very slow >200 min/in	S PS U	S PS U
8. OTHER (Specify)	S PS U flood	S PS U ——	S PS U	S PS U
9. EVALUATION*	wet soil	water table		
10. USE	Chance	Error		


S - Suitable PS - Provisionally Suitable U - Unsuitable

*Explain on Back (Include: Soil areas, property lines, roads, buildings, slopes, cuts, fills, waterbodies, etc.)

Additional Comments: Based on this investigation the lot would have soils demonstrating high water table for installation of a septic tank system.

Recommended By: Edward Cassidy
Title: Soil Scientist July 12, 1977

DHS Form 2601 (2/77)
Sanitation


150'
Enon
2
302'
340'
Chevalier
1
156'
Timber Ridge Dr.

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

DATE ISSUED
1. 7-13-77
2. _____
3. _____

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

SIP NO. 12829
T.O. NO. P.O.135-351-01
MAP DATE _____

NAME OF OWNER **Bob McLemore & Company, Inc.**

ADDRESS OF OWNER **P.O. Box 25746, Charlotte, NC 28212**

LOCATION OF LOT **Timber Ridge Drive, Lot 21, Block J**

The lot described above is not recommended for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge due to the following:

Soil Structure Massive.

Soil Permeability Unsuitable.

John R. Adkisson

John R. Adkisson, Environmentalist
On Premises Waste Disposal Section

JRA:glr

(Stencil No.)
EHD 398
8/74

FORM NO.
E-19-8-21-74