Date Received 8-8-83

RECEIVED
AUG 8 1983
ENVIRONMENTAL HEALTH

APT No. 19939
T.P. No. 033-064-01
Map Date

MECK COUNTY DEPARTMENT OF
RECEIVED
AUG
ENVIRONMENTAL HEALTH

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER GRIFFIN (LAST) J. (FIRST) J. (MIDDLE)

2) ADDRESS OF OWNER 219 Box 197 ZIP 28208

3) PHONE NO. Home 394-7656 Office


4) LOCATION OF PROPERTY Skies Talon Dr Holly Huntersville (STREET OR COUNTY ROAD)

5) SUBDIVISION LOT NO. BLOCK NO.

MAP BOOK NO 38 94 PAGE NO. 259

6) DEED REFERENCE DEED BOOK 1890 PAGE NO. 160

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge.



7) ACCURATELY DIAGRAM & DIMENSION LOT

OWNER

EHD-5-76

Environmental Health Department's Copy

Repair Request

8/31/82

DEPARTMENT OF ENVIRONMENTAL HEALTH
MECKLENBURG COUNTY,
NORTH CAROLINA

SITE EVALUATION

S.I.R. NO. 9 B339

T.C. NO. PO 033-064-01

(Ground Absorption Sewage Disposal)

OWNER: J. B. Griffin
ADDRESS: R-7 Box 197 28208

PLAT NO:
LOT SIZE: P.O. 42A

LOCATION OF SITE: Mt. Holly Huntersville Rd

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	(PS) 2-6	(PS) 2-4	PS	PS
2. SOIL TEXTURE (12-36 inches) Sandy, Loamy, Clayey (Note 2-1 Clay)	(PS) Clayey	(PS) Clayey	PS	PS
3. SOIL STRUCTURE (12-36 inches)	(PS) Blocky	(PS) Blocky	PS	PS
4. SOIL DEPTH (inches)	(PS) 45'	(PS) 36-40	PS	PS
5. RESTRICTIVE HORIZONS (Inches) (Impervious strata, Rock)	(PS) None	(PS) None	PS	PS
6. SOIL DRAINAGE/GROUNDWATER (external and internal)	(PS) Adequate	PS Surface Drainage (U) Problem	PS	PS
7. OTHER (Specify)	PS	PS	PS	PS
8. SOIL GROUP	IIe	IVa		
9. SITE CLASSIFICATION	Provisionally	Unsuitable		
10. SOIL SERIES	Cecil	Cecil		

S - Suitable PS - Provisionally Suitable U - Unsuitable

**See Diagram on Back (includes: soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slopes)

Recommendations/Comments: Soil Has been Abused By Parking Junk Cars on it - But Still is acceptable


Described by: W. B. Kagnon
Title: Soil Scientist

Date: 8-15-83

EHD 539 (Revised: 6/82)

file

Mt. Holly Huntersville Rd



Wants To Install New
Tank & Line