Date Received 9-10-73

APT No. 6961

T. C. No.

Map Date

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER Woodruff (LAST) John (FIRST) G. (MIDDLE)

2) ADDRESS OF OWNER 4225 Windwood Circle ZIP 28211.

3) PHONE NO Home 366-4257 Office None Retired.


4) LOCATION OF PROPERTY Windwood Circle (STREET OR COUNTY ROAD)

5) SUBDIVISION Windwood Circle LOT NO 35 BLOCK NO

MAP BOOK NO 1783 PAGE NO 96

6) DEED REFERENCE DEED BOOK PAGE NO

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

OWNER John G. Woodruff. John G. Woodruff

FORM NO. E-1-9-1-72

HEALTH DEPARTMENT'S COPY

MECKLENBURG COUNTY HEALTH DEPARTMENT
INTER-OFFICE COMMUNICATION

DATE: September 11, 1973

TO: Luther Bridgeman
Environmentalist

FROM: W. Everette Lynn, Jr. W.E.L.
Soil Scientist

SUBJECT: APT: #6961 (John Woodruff)
Windwood Circle, Lot No. 35
7/25/73

Soils were found to be of the Iredell and Wilkes series. These soils have very plastic and sticky clay subsoils which contain swelling clay minerals. The Iredell soils have a perched high water table during periods of high rainfall. The Wilkes soils are shallow to impervious weathered rock material. These factors result in inadequately slow percolation rate and permeability.

Based on these observations, it is recommended that the lot be disapproved for installation of a septic tank system.

WEL:dcr