Date Received 6/2/71

MECK CO. DEPARTMENT OF [illegible]

APT No. 12532

T. C. No. 033-132-06

Map Date _____

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER BLYTHE, ROBERT FRANKLIN
(LAST, FIRST, MIDDLE)

2) ADDRESS OF OWNER RT. 9, BOX 411-B, CHARLOTTE, N.C. ZIP 28208

3) PHONE NO Home 392-5185 Office 527-3090


4) LOCATION OF PROPERTY ~~MARINDA~~ MIRANDA RD. (.8 MILE OFF BEATTIES FORD RD)
STREET OR COUNTY ROAD

5) SUBDIVISION _____ LOT NO _____ BLOCK NO. _____

MAP BOOK NO _____ PAGE NO _____

6) DEED REFERENCE DEED BOOK 2021 PAGE NO. 263

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

SEE ATTACHED MAP

R. F. Blythe
OWNER

EHD-5-76

Environmental Health Department's Copy

SOIL INVESTIGATION REPORT

Date of Investigation June 8 1977 APT NO. 12532

Owner Robert L. Blythe P.I.C. 633-132-06

Location of Property Miranda Rd

Soil Suitability Ratings


Soil Properties	Soil 1	Soil 2	Soil 3	Soil 4
1. Soil Series	Corralitos Aptos Watsonville			
2. Soil Slope	Suitable 2-6%			
3. Soil Depth	[illegible]			
4. Soil Texture	Predominantly Suitable Some Adobe Clay			
5. Soil Structure	Predominantly Suitable Blocky			
6. Restrictive Horizons				
7. Soil Drainage	[illegible]			
8. Soil Permeability (Percolation Rate)	Predominantly Suitable Moderate Rapid			
9. Other	Some Areas of Acceptable Soil	Poor Soil		
10. Overall Rating	Predominantly Suitable			

Recommendations (Generally Favorable) Based on this investigation a limited area is available for the installation of septic tank and leach lines. The leach lines should be placed in the more permeable soils of the area.

Soil Engineer William E. Wilson

3/[illegible]/75
P.D. 509

DIAGRAM OF PROPERTY



3/18/75
EHD 539