Date Received 5/12/77

APT No. 12455
P.C.
T. C. No. 23-11-1-2

Map Date

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER BOB McLEMORE & CO, INC
(LAST FIRST MIDDLE)

2) ADDRESS OF OWNER P O Box 25746 CHAR. ZIP 28212

3) PHONE NO Home _____ Office 545-6111


4) LOCATION OF PROPERTY TILLEY MORRIS RD
(STREET OR COUNTY ROAD)

5) SUBDIVISION PROVIDENCE RIDGE LOT NO 9 BLOCK NO B

MAP BOOK NO _____ PAGE NO. _____

6) DEED REFERENCE DEED BOOK _____ PAGE NO. _____

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

Robert Ordell
OWNER

FORM NO. BE 1-3M-6-75

HEALTH DEPARTMENT'S COPY

SOIL INVESTIGATION REPORT

Date of Investigation May 18, 1977 APT NO. 12455

Owner Bob McLemore & Co. Inc.

Location of Property Providence Ridge Lot No. 6 Block B

Soil Suitability Ratings Tax Code No. P.O. 251-101-01


Soil Properties	Soil 1	Soil 2	Soil 3	Soil 4
1. Soil Series	Chewacla			
2. Soil Slope	—			
3. Soil Depth	—			
4. Soil Texture	—			
5. Soil Structure				
6. Restrictive Horizons				
7. Soil Drainage	unsuitable poorly drained			
8. Soil Permeability (Percolation Rate)	unsuitable seasonal high water table < 18" from surface			
9. Other	unsuitable floods			
10. Overall Rating	unsuitable			

Recommendations Based on this investigation, the lot was found not to have an acceptable area of acceptable soils for installation of a septic tank system.

Soil Scientist W. Edward Crawford

3/10/75

DIAGRAM OF PROPERTY



3/18/75
EHD 539

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE NORTH CAROLINA 28203

5-23-77

12455
P.O. 231-101-01

Bob McLemore & Company, Inc.
P.O. Box 25746, Charlotte, NC 28212
Tilley Morris Road, Lot 6, Block B

Soil Permeability Unsuitable.

John R. Adkisson
John R. Adkisson, Environmentalist
On Premises Waste Disposal Section

JRA: glr