Copy to Mady Construction Co.
3549 N. Sharon Amity, Suite 303, Charlotte, NC 28205

Date Received 9/12/78

MECK COUNTY DEPARTMENT OF
RECEIVED
SEP 12 1978
ENVIRONMENTAL HEALTH

APT No. 14537

T. C. No. 037-076-06

Map Date 9.7.78

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Lawings, Inc.
(LAST / FIRST / MIDDLE)

2) ADDRESS OF OWNER 5521 Belhaven Blvd. Charlotte, N. C. ZIP 28216

3) PHONE NO Home 394-4915 Office 399-6372


4) LOCATION OF PROPERTY Kinghurst Drive
(STREET OR COUNTY ROAD)

5) SUBDIVISION Edmore Estates LOT NO 1 ~~XX~~ BLOCK NO. ~~XX~~ 9

MAP BOOK NO 14 PAGE NO 167

6) DEED REFERENCE DEED BOOK 2907 PAGE NO 168

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

VAL ROSE DR.

Lawings, Inc.
By: M. Wayne Hasty
OWNER

Environmental Health Department's Copy

NORTH CAROLINA
DEPARTMENT OF HUMAN RESOURCES
DIVISION OF HEALTH SERVICES
RALEIGH, NORTH CAROLINA

APPENDIX H
SITE EVALUATION

APT 14537
TC 037-078-06
Lot 1, Block 4

(Ground Absorption Sewage Disposal)

OWNER: Jennings Enc. DATE REQUESTED:
ADDRESS: 5521 Bellhaven Blvd PLAT NO.:
COUNTY: Charlotte, N.C. LOT SIZE: 43,560
LOCATION OF SITE: Wayhurst Ln.

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	(S) 2-15% PS U	S PS U	S PS U	S PS U +
2. SOIL TEXTURE (12-36 in.) (Sandy, loamy, clayey, Note 2:1, Clay)	S PS 2-1 (U) clay	S PS U	S PS U	S PS U
3. SOIL STRUCTURE (12.36 in.) (Clayey Soils)	S PS Massive (U)	S PS U	S PS U	S PS U
4. SOIL DEPTH (In.)	(S) 48" PS U	S PS U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (In.) (Impervious Strata, Rock)	(S) None PS U	S PS U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (External & Internal) *	S perched PS water (U) Table	S PS U	S PS U	S PS U
7. SOIL PERMEABILITY (Percolation Rate)	S PS 0 sec (U)	S PS U	S PS U	S PS U
8. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U
9. SITE CLASSIFICATION	U-S.T. Table			
SOIL SERIES	Helena			

S - Suitable PS - Provisionally Suitable U - Unsuitable

* See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slope patterns, etc)

Recommendations/Comments: * The lot serves As A Drainageway for water coming off of Wayhurst Drive

Described By: William H. Harlan

Title: Soil Scientist Date: 9-26-78

DHS Form 2601 (2/77)
Sanitation

#2

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

SIR.NO. 14537
T.C. NO. 037-076-06
MAP DATE 6-7-78
DATE 10-2-78

NAME OF OWNER Lawings, Inc.

ADDRESS OF OWNER 5521 Belhaven Boulevard, Charlotte, NC 28216

LOCATION OF LOT Kinghurst Drive, Lot 1, Block 9, Edmore Estates

As determined under the Rules and Regulations promulgated by the Commission for Health Services, Division of Health Services, North Carolina Department of Human Resources, Raleigh, North Carolina, the soils on the lot described above were found to be unsuitable for the installation of an individual septic tank-soil absorption system. This site cannot be approved for a septic tank system due to the following reason:

Soil Structure Massive.
Soil Permeability Unsuitable.

John R. Adkisson

John R. Adkisson, Environmentalist
On Premises Waste Disposal Section

EHD 308
7/ 7

R