Date Received 8-9-84

MECK CO[illegible] Y DEPARTMENT OF
RECEIVED
[illegible] 1984
ENVIRONMENTAL HEALTH

SIR No. 21289
T.P. No. 035-121-14
Map Date 1

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER STANSBERRY (LAST) RAY (FIRST) GLENN (MIDDLE)

2) ADDRESS OF OWNER 5438 MARENGO CIR. - CHARLOTTE ZIP 28216

3) PHONE NO. Home 392-5902 Office 392-5902


4) LOCATION OF PROPERTY [redacted] ROSEWOOD DRIVE (STREET OR COUNTY ROAD)

5) SUBDIVISION McCLURE ACRES LOT NO 3 BLOCK NO PORTION OF "A"

MAP BOOK NO 7 PAGE NO 629

6) DEED REFERENCE DEED BOOK [illegible] PAGE NO [illegible]

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

Ray Glenn Stansberry
OWNER

EHD-5-76

ENVIRONMENTAL HEALTH DEPARTMENT'S COPY

DEPARTMENT OF ENVIRONMENTAL HEALTH
MECKLENBURG COUNTY,
NORTH CAROLINA

SITE EVALUATION

S.I.R. NO. 21289

T.C. NO. P.O. 035-ME-14

(Ground Absorption Sewage Disposal)

OWNER: RAY STANSBERRY PLAT NO:
ADDRESS: 5438 MARENBO Cir. LOT SIZE: 20,000 sq. ft.
LOCATION OF SITE: 2216 Rozwood Drive

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	S (PS) 2-10 U	S PS U	S PS U	S PS U
2. SOIL TEXTURE (12-36 inches) Sandy, Loamy, Clayey (Note 2-1 Clay)	S Saprolite PS (U)	S PS U	S PS U	S PS U
3. SOIL STRUCTURE (12-36 inches)	S Decayed PS Rock (U)	S PS U	S PS U	S PS U
4. SOIL DEPTH (inches)	S PS 1-2' (U)	S PS U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (Inches) (Impervious strata, Rock)	S (PS) None U	S PS U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (external and internal)	S PS Slod (U)	S PS U	S PS U	S PS U
7. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U
8. SOIL GROUP	None			
9. SITE CLASSIFICATION	Unsuitable			
10. SOIL SERIES	Saprolite - A-C. (Not Enough Soil For Wilkes - No Clay			

S - Suitable PS - Provisionally Suitable U - Unsuitable


**See Diagram on Back (includes: soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slopes)

Recommendations/Comments:

Described by: Will Ramsey
Title: Soil Scientist

Date: 9-4-84

34


134
Saprolite
2-4
Saprolite
2-10
157
Saprolite
2-4
Rozwood Dr.

MECKLENBURG COUNTY
Department of Environmental Health

September 6, 1984

Mr. Ray Stansberry
5438 Marengo Circle
Charlotte, N. C. 28216

Re: Property located at Rozwood Drive

Dear Sir:

At your request a soils investigation was conducted on the property designated above. Results of this investigation showed the site to be classified as unsuitable under criteria as set forth in Section .1900 of the North Carolina Administrative Code, Title 10, Department of Human Resources, Chapter 10, Division of Health Services; Sanitary Engineering Section, Subchapter 10A, Sanitation.

The soil on this property is not suitable for use with any conventional system, modified or alternative, with which I am aware.

If I can be of assistance, please feel free to call.

Sincerely,

Bill D. Hardister, Jr.
Environmental Health Supervisor
On Premises Waste Disposal Section

BDH/sce

Enclosure
SIR 21294