Date Received 10/24/79

APT No 16265

T C No 108-082-03

Map Date 5/23/78

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Brumble (LAST) William (FIRST) Bruce (MIDDLE)

2) ADDRESS OF OWNER 2115 Lakemont Ave ZIP 28215

3) PHONE NO Home 377-1456 Office


4) LOCATION OF PROPERTY Myra (STREET OR COUNTY ROAD) Way

5) SUBDIVISION White Forest LOT NO 47 BLOCK NO

MAP BOOK NO 7 PAGE NO 695

6) DEED REFERENCE DEED BOOK 3111 PAGE NO 155

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface soil absorption effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

W. B. Brumble
OWNER

EHD-5-76

Environmental Health Department's Copy

S. I. R. NO. 16265

NORTH CAROLINA
DEPARTMENT OF HUMAN RESOURCES
DIVISION OF HEALTH SERVICES
RALEIGH, NORTH CAROLINA

APPENDIX B
SITE EVALUATION

T. C. # 108-082-03

(Cross Absorption Sewage Disposal)

OWNER William B. BRUMBLE DATE REQUESTED 10-24-79
ADDRESS 215 LABURNUM AVE PLAT NO.:
COUNTY CHARLOTTE LOT SIZE: 20,000
LOCATION OF SITE: MYRA WAY LOT 40

FACTORS		AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	S		S	S	S
	PS	2-10	PS	PS	PS
	U		U	U	U
2. SOIL TEXTURE (12-36 in.) (Sandy loamy clayey, Note 2.1 Clay)	S		S	S	S
	PS	2-1 clay	PS	PS	PS
	U	Saprolite	U	U	U
3. SOIL STRUCTURE (12-36 in.) (Clayey Soils)	S		S	S	S
	PS	MASSIVE	PS	PS	PS
	U		U	U	U
4. SOIL DEPTH (In.)	S		S	S	S
	PS	48	PS	PS	PS
	U		U	U	U
5. RESTRICTIVE HORIZONS (In.) (Impervious Strata Rock)	S		S	S	S
	PS	Saprolite	PS	PS	PS
	U		U	U	U
6. SOIL WETNESS/WATER TABLE (External Internal)	S		S	S	S
	PS	SLOW	PS	PS	PS
	U		U	U	U
7. SOIL PERMEABILITY (Percolation Rate)	S		S	S	S
	PS	SLOW	PS	PS	PS
	U		U	U	U
8. OTHER (Specify)	S		S	S	S
	PS		PS	PS	PS
	U		U	U	U
9. SITE CLASSIFICATION		Unsuitable			

SOIL SERIES: Wilkes

S - Suitable PS - Provisionally Suitable U - Unsuitable

* See Diagram on Back (Include Soil areas property lines roads streams gullies rock areas fill areas, wells, water bodies, slope patterns etc


Recommendations/Comments:

Described By: W. B. Ramsey

Title: Soil Scientist Date: 10-31-79

DHS Form 2691
Sanitation
EHD 539 (3/79)

3


Lot 40
100
WILKES
2-10
Complex
Slopes
200'
Myra Way
Wood Rd

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

S.I.R. # 16265

T.C. # 108-082-03

DATE Nov. 2, 1979

NAME OF OWNER Brumble, William B.

ADDRESS OF OWNER 2115 Laburnum Avenue, Charlotte, NC 28205

LOCATION OF LOT HYRA WAY, lot 40 (White Forest)

As determined under the Rules and Regulations promulgated by the Commission for Health Services, Division of Health Services, North Carolina Department of Human Resources, Raleigh, North Carolina, the soils on the lot described above were found to be unsuitable for the installation of an individual septic tank - soil absorption system, due to the following reason:

Soil Structure Massive

Soil Permeability Unsuitable

John R. Adkisson

John R. Adkisson, Environmentalist