Date Received 10/8/79

APT No 16204

T. C. No 055-158-12

Map Date _____

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Anderson (LAST) Eula (FIRST) Lee (MIDDLE)

2) ADDRESS OF OWNER Rt 5 Box 94451 Charlotte ZIP 28208

3) PHONE NO Home 399-1456 Office —


4) LOCATION OF PROPERTY Centergrove Ln. (STREET OR COUNTY ROAD)

5) SUBDIVISION Berryhill Township LOT NO 126 + 135 BLOCK NO _____

MAP BOOK NO 4 PAGE NO 501 Plat Shadybrook Map

6) DEED REFERENCE DEED BOOK 3420 PAGE NO 174

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if this lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface soil absorption effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

Eula Lee Anderson
OWNER

EHD-5-76

Environmental Health Department's Copy

S.I.R. NO. 16 304

NORTH CAROLINA
DEPARTMENT OF HUMAN RESOURCES
DIVISION OF HEALTH SERVICES
RALEIGH, NORTH CAROLINA

APPENDIX H
SITE EVALUATION

T.C. # 353 [illegible]-12

(Ground Absorption Sewage Disposal)

OWNER: Eula Joe Culverson
ADDRESS: R.F.D. Box 94431, Charlotte
COUNTY:
LOCATION OF SITE: Centergrove Farm

DATE REQUESTED:
PLAT NO.:
LOT SIZE: 10,035

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	(S) PS 2-10% U	S PS U	S PS U	S PS U
2. SOIL TEXTURE (12-36 in.) (Sandy, loamy, clayey, Note 2:1, Clay)	S PS 2-1 (U) clay	S PS U	S PS U	S PS U
3. SOIL STRUCTURE (12.36 in.) (Clayey Soils)	S PS Massive (U)	S PS U	S PS U	S PS U
4. SOIL DEPTH (In.)	S PS ~48" (U)	S PS U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (In.) (Imprevious Strata, Rock)	(S) None PS U	S PS U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (External & Internal)	(S) 76" to ground PS water U	S PS U	S PS U	S PS U
7. SOIL PERMEABILITY (Percolation Rate)	S PS unsuitable (U)	S PS U	S PS U	S PS U
8. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U
9. SITE CLASSIFICATION	unsuitable			
SOIL SERIES	Enon			

S - Suitable PS - Provisionally Suitable U - Unsuitable


* See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slope patterns, etc)

Recommendations/Comments:

Described By: William A. Mackie
Title: Soil Scientist Date: 10-19-79

DHS Form 2604 (2/77)
Sanitation

2


60
114
Eau
91
95
Contrayerve

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

S.I.R. # 16208

T.C. # 053-158-12

DATE October 22, 1979

NAME OF OWNER Anderson, Eula Lee

ADDRESS OF OWNER Route 5, Box 94431, Charlotte, NC 28208

LOCATION OF LOT Centergrove Lane, lots 126 and 125

As determined under the Rules and Regulations promulgated by the Commission for Health Services, Division of Health Services, North Carolina Department of Human Resources, Raleigh, North Carolina, the soils on the lot described above were found to be unsuitable for the installation of an individual septic tank - soil absorption system, due to the following reason:

Soil Structure Massive

Soil Permeability Unsuitable

Site Classification Unsuitable

John R. Adkisson, Environmentalist