Date Received 5/25/77

MAY 2

APT No. 12504

T. C. No. 025-105-22, 23

Map Date 2-21-75

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Sharp (LAST) William (FIRST) Ward (MIDDLE)

2) ADDRESS OF OWNER 1214 Sunnyside Drive ZIP 28208

3) PHONE NO Home 392-0711 Office


4) LOCATION OF PROPERTY Long Creek → Lake Road - Woodland Circle (STREET OR COUNTY ROAD)

5) SUBDIVISION Forest Hills LOT NO 10 & 11 BLOCK NO. C

MAP BOOK NO PAGE NO

6) DEED REFERENCE DEED BOOK PAGE NO

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and on-site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface soil absorption effluent discharge.



7) ACCURATELY DIAGRAM & DIMENSION LOT

William L. Sharp
OWNER

EHD-5-76

Environmental Health Department's Copy

SOIL INVESTIGATION REPORT

Date of Investigation June 9, 1977 APT NO. 12504

Owner William Ewald Abreu Tax No. 025-105-2233

Location of Property Ledbetter Circle - East Rim Lot's 10 & 11

Soil Suitability Ratings

Soil Properties	Soil 1	Soil 2	Soil 3	Soil 4
1. Soil Series	Enon			
2. Soil Slope				
3. Soil Depth				
4. Soil Texture				
5. Soil Structure				
6. Restrictive Horizons				
7. Soil Drainage				
8. Soil Permeability (Percolation Rate)				
9. Other				
10. Overall Rating				

Recommendations Soil & Site investigation of lot was found suitable for installation of a septic tank system.


See Diagram on Back

William A. Martin
Soil Scientist

3/10/75
TMD 509

33
.5 X
1.1 0

DIAGRAM OF PROPERTY



3/18/75
EHD 539

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE NORTH CAROLINA 28203

DATE ISSUED
1. 6-13-77
2. _____
3. _____

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

SIP NO. 12504
T.C. NO. 025-105-23,22
MAP DATE 2-21-75

NAME OF OWNER Shoup, William Donald

ADDRESS OF OWNER 1208 Saratoga Drive, Charlotte, NC 28208

LOCATION OF LOT Woodland Circle, Lot 10 & 11, Block C

The lot described above is not recommended for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge due to the following:

Soil Structure Unsuitable.

Soil Permeability Unsuitable.

John R. Adkisson, Environmentalist
On Premises Waste Disposal Section

JRA: glr

(Stencil No.)
EHD 388
8/74

FORM No.
E-1?-8-21-74

SOIL INVESTIGATION REPORT

Date of Investigation June 9, 1977 APT NO. 12504

Owner Carlson Developers, Inc. T.P. 025-105-22 025-105-23

Location of Property Woodland Circle Lots 10 & 11

Soil Suitability Ratings

Soil Properties	Soil 1	Soil 2	Soil 3	Soil 4
1. Soil Series	Enon			
2. Soil Slope	Suitable 2-6%			
3. Soil Depth	Unsuitable 36"-42"			
4. Soil Texture	Unsuitable 2:1 Expanding Clay			
5. Soil Structure	Unsuitable Massive			
6. Restrictive Horizons				
7. Soil Drainage	Suitable 24" To Water Table			
8. Soil Permeability (Percolation Rate)	Unsuitable 6 Slow 120 min/in			
9. Other				
10. Overall Rating	Unsuitable			


Recommendations Based on the investigation, this site is not considered to be suitable for the installation of septic tank system.

See diagram on back

Wm. B. Marden
Soil Scientist

3/10/75
EHD 539

DIAGRAM OF PROPERTY



3/18/75
EHD 539

Date Received _____

APT No. 12504
025-105-22
T. C. No. 025-105-23

Map Date _____

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Carolina Developers, Inc.
(LAST, FIRST, MIDDLE)

2) ADDRESS OF OWNER 409 Johnston Bldg, 212 S. Tryon Street ZIP 28281
Charlotte, North Carolina

3) PHONE NO Home _____ Office 332--5431


4) LOCATION OF PROPERTY Woodland Circle (Off Rd #2113)
(STREET OR COUNTY ROAD)

5) SUBDIVISION Forest Acres #1 LOT NO 10 & 11 BLOCK NO C

MAP BOOK NO 10 PAGE NO 271

6) DEED REFERENCE DEED BOOK _____ PAGE NO _____

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and inspection of the lot hereinafter described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface soil absorption effluent disposal.



7) ACCURATELY DIAGRAM & DIMENSION LOT

OWNER Freeman L. Harsey, President

EHD 5-76

Environmental Health Department's Copy

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE NORTH CAROLINA 28203

DATE ISSUED
1. 6-22-77
2. _____
3. _____

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

SIP NO. 12504
T.C. NO. 025-105-22,23
MAP DATE _____

NAME OF OWNER **Carolina Developers, Inc.**

ADDRESS OF OWNER **409 Johnston Bldg., 212 S. Tryon St., Charlotte, NC 28281**

LOCATION OF LOT **Woodland Circle, Lots 10 & 11, Block C**

The lot described above is not recommended for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge due to the following:

Soil Structure Unsuitable.

Soil Permeability Unsuitable.

John R. Adkisson, Environmentalist
On Premises Waste Disposal Section

JRA: glr

(Stencil No.)
ENE 389
8/74

FORM NO.
E-19-8-21-74

R