Date Received 1-30-79

APT No. 15059

P.O.
T. C. No. 105-153-07

Map Date _____

# MECKLENBURG COUNTY
# DEPARTMENT OF ENVIRONMENTAL HEALTH

## APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Coleman (LAST) Warren (FIRST) Preston (MIDDLE)

2) ADDRESS OF OWNER 4900 Rocky River Rd East ZIP 28215

3) PHONE NO. Home 592-2291 Office Same


4) LOCATION OF PROPERTY Rocky River Rd East (STREET OR COUNTY ROAD)

5) SUBDIVISION Briarside LOT NO 8 BLOCK NO _____

MAP BOOK NO _____ PAGE NO _____

6) DEED REFERENCE DEED BOOK _____ PAGE NO. _____

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption effluent discharge




7) ACCURATELY DIAGRAM & DIMENSION LOT

_____
OWNER

EHD-5-76

Environmental Health Department's Copy

NORTH CAROLINA
DEPARTMENT OF HUMAN RESOURCES
DIVISION OF HEALTH SERVICES
RALEIGH, NORTH CAROLINA

APPENDIX H
SITE EVALUATION

S.I.R. No. 15659

(Ground Absorption Sewage Disposal)

OWNER: Steven P. Coleman
ADDRESS: 4906 Ann Rd.
COUNTY: Charlotte, NC
LOCATION OF SITE: Proposed Lot Unimproved

DATE REQUESTED:
PLAT NO.: Po 105-15307 Lot 16
LOT SIZE: 32,466

| FACTORS | AREA 1 | AREA 2 | AREA 3 | AREA 4 |
|---|---|---|---|---|
| 1. SLOPE (%) | (S) PS U 2-8% | S PS U | S PS U | S PS U |
| 2. SOIL TEXTURE (12-36 in.) (Sandy, loamy, clayey, Note 2:1, Clay) | S PS (U) 2-1 clay | S PS U | S PS U | S PS U |
| 3. SOIL STRUCTURE (12-36 in.) (Clayey Soils) | S (PS) massive (U) | S PS U | S PS U | S PS U |
| 4. SOIL DEPTH (In.) | (S) 48" PS U | S PS U | S PS U | S PS U |
| 5. RESTRICTIVE HORIZONS (In.) (Impervious Strata, Rock) | (S) None PS U | S PS U | S PS U | S PS U |
| 6. SOIL DRAINAGE/GROUNDWATER (External & Internal) | S Seasonal PS Perched (U) Water Table | S PS U | S PS U | S PS U |
| 7. SOIL PERMEABILITY (Percolation Rate) | S (PS) U slow (U) | S PS U | S PS U | S PS U |
| 8. OTHER (Specify) | S PS U | S PS U | S PS U | S PS U |
| 9. SITE CLASSIFICATION | unsuitable | | | |
| SOIL SERIES | Helena | | | |

S - Suitable PS - Provisionally Suitable U - Unsuitable

* See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slope patterns)


Recommendations/Comments:

Described By: William R. Wallis

Title: Soil Scientist Date: 2-14-79

dhs form 2601 (1/79)
Sanitation

2


230'
133'
125'
230'

**MECKLENBURG COUNTY**
**DEPARTMENT OF ENVIRONMENTAL HEALTH**
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

SIR.NO. 15059
T.C. NO. po 105-153-07
MAP DATE
DATE February 20, 1979

NAME OF OWNER Coleman, Warren P.

ADDRESS OF OWNER 4900 Rocky River Road, East

LOCATION OF LOT Rocky River Road, East Lot #8

As determined under the Rules and Regulations promulgated by the Commission for Health Services, Division of Health Services, North Carolina Department of Human Resources, Raleigh, North Carolina, the soils on the lot described above were found to be unsuitable for the installation of an individual septic tank-soil absorption system. This site cannot be approved for a septic tank system due to the following reason:

Soil Structure Massive

Perched Water Table

Soil Permeability Unsuitable

Site Classification Unsuitable

Stephen J. Wood, Environmentalist

END 398
7/77