Date Received 5/1/[illegible]

APT No [illegible]

T C No [illegible]

Map Date [illegible]

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER [illegible] (LAST) [illegible] (FIRST) [illegible] (MIDDLE)

2) ADDRESS OF OWNER [illegible] ZIP [illegible]

3) PHONE NO Home 399-3942 Office [illegible]


4) LOCATION OF PROPERTY [illegible] (STREET OR COUNTY ROAD)

5) SUBDIVISION OAKHAZ ACRES LOT NO 11 BLOCK NO E

MAP BOOK NO 8 PAGE NO 213

6) DEED REFERENCE DEED BOOK 2564 PAGE NO 431

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption effluent disposal.



SIMPSON RD

OWNER Steve Griffin

FORM NO E-1-8-1-72

HEALTH DEPARTMENT'S COPY

SOIL INVESTIGATION REPORT

Date of Investigation May 23 [illegible] APT NO. 124-5

Owner [illegible] T.C. 33-[illegible]

Location of Property [illegible] Lot [illegible]

Soil Suitability Ratings

Soil Properties	Soil 1	Soil 2	Soil 3	Soil 4
1. Soil Series				
2. Soil Slope				
3. Soil Depth				
4. Soil Texture				
5. Soil Structure				
6. Restrictive Horizons				
7. Soil Drainage				
8. Soil Permeability (Percolation Rate)				
9. Other				
10. Overall Rating				

Recommendations [illegible]

[illegible]


[illegible]

[illegible]

[illegible]

3[illegible]75
[illegible]

DIAGRAM OF PROPERTY



3/18/75
EHD 539

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE NORTH CAROLINA 28203

DATE ISSUED
1. 5-27-77
2.
3.

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

SIP NO. 12415
T.C. NO. 033-075-02
L P DATE

NAME OF OWNER **Griffin, Steven A.**

ADDRESS OF OWNER **Rt.9, Box 217E, Charlotte, NC 28208**

LOCATION OF LOT **Simpson Road, Lot 11, Block E**

The lot described above is not recommended for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge due to the following:

Soil Permeability Unsuitable.

Percolation rate in excess of 200 min/in.

John R. Adkisson, Environmentalist
On Premises Waste Disposal Section

JRA: glr

(Stencil No.)
EHD 369
8/74

FORM NO.
E-1[illegible]-8-21-7[illegible]

Date Received 1/23/79

MECK COUNTY DEPARTMENT OF
RECEIVED
JAN 23 1979
ENVIRONMENTAL

APT No. 1215
T C No 033-075-02
Map Date 11/8/77

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER GRIFFIN (LAST) STEVEN (FIRST) M. (MIDDLE)

2) ADDRESS OF OWNER AT. 1 BOX 217E CHARLOTTE, NC ZIP 28208

3) PHONE NO Home 399-3948 Office —


4) LOCATION OF PROPERTY SIMPSON RD. (STREET OR COUNTY ROAD)

5) SUBDIVISION OAKDALE ACRES LOT NO 11 BLOCK NO E

MAP BOOK NO 8 PAGE NO 273

6) DEED REFERENCE DEED BOOK 2584 PAGE NO 401

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and on-site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface soil absorption effluent discharge.



7) ACCURATELY DIAGRAM & DIMENSION LOT

SIMPSON RD

OWNER Steve Griffin

FORM NO E-1-8-1-72

HEALTH DEPARTMENT'S COPY

NORTH CAROLINA
DEPARTMENT OF HUMAN RESOURCES
DIVISION OF HEALTH SERVICES
RALEIGH, NORTH CAROLINA

APPENDIX H
SITE EVALUATION

S.I.R. No. 12415

(Ground Absorption Sewage Disposal)

OWNER: Steven N C [illegible] (Lot 11) / Tibal Gaston (Lot 10)
ADDRESS: Rt 9 Box 211E
COUNTY: Charlotte, N.C. 28206
LOCATION OF SITE: Simpson Rd.

DATE REQUESTED:
PLAT NO.: 033-075-02 (Lot 11), 033-075-01 (Lot 10)
LOT SIZE: 35,000

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	S 2+2% PS U	S 2+2% PS U	S 2-4 PS U	S Complex PS Slopes U
2. SOIL TEXTURE (12-36 in.) (Sandy, loamy, clayey, Note 2:1, Clay)	S 2-1 PS Clay U	S 2-1 PS Clay U	S 2-1 PS Clay U	S 2-1 PS Clay U
3. SOIL STRUCTURE (12-36 in.) (Clayey Soils)	S Massive PS U	S Massive PS U	S Massive PS U	S Massive PS U
4. SOIL DEPTH (In.)	S 48" PS U	S 48" PS U	S 36" PS U	S Depth Variable PS U
5. RESTRICTIVE HORIZONS (In.) (Impervious Strata, Rock)	S None PS U	S None PS U	S None PS U	S None PS U
6. SOIL DRAINAGE/GROUNDWATER (External & Internal)	S Seasonal PS Perched water U Table	S Seasonal PS Perched water U Table	S Seasonal PS Perched water U Table	S Eroded Areas PS Act As U Drainage Ways
7. SOIL PERMEABILITY (Percolation Rate)	S Slow PS U Slow	S Slow PS U Slow	S Slow PS U Slow	S Slow PS U Slow
8. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U
9. SITE CLASSIFICATION	Unsuitable	Unsuitable	Unsuitable	Unsuitable
SOIL SERIES	Helena	Enon w/ Iredell	Iredell	Enon w/ Iredell Eroded

S - Suitable PS - Provisionally Suitable U - Unsuitable

* See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slope patterns)


Recommendations/Comments: Combined Report - SIR's 12489 & 12415

Described By: William R. Martin

Title: Soil Scientist Date: 2-8-79

dhs form 2601 (1/79)
Sanitation

2


w Ikns
100'
Encr w Ikns
351'
351
Helena
gvll.rd
Encr w Ikns
100'
Simpson Rd

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM WITH SUBSURFACE, SOIL ABSORPTION, EFFLUENT DISCHARGE

SIR.NO. 12415
T.C. NO. 033-075-02
MAP DATE
DATE January 24, 1979

NAME OF OWNER Griffin, Steven A.

ADDRESS OF OWNER Route 9, Box 217 - E, Charlotte, N.C. 28208

LOCATION OF LOT Simpson Road, Lot 11, Block E

As determined under the Rules and Regulations promulgated by the Commission for Health Services, Division of Health Services, North Carolina Department of Human Resources, Raleigh, North Carolina, the soils on the lot described above were found to be unsuitable for the installation of an individual septic tank-soil absorption system. This site cannot be approved for a septic tank system due to the following reason:

Soil Depth Unsuitable

Soil Permeability Unsuitable

Soil Structure Massive

John R. Adkisson, Environmentalist

EHD 398
7/77

Date Received 2/2/79

MECK COUNTY DEPARTMENT OF
RECEIVED
FEB 1 1979
ENVIRONMENTAL HEALTH

APT No.

T. C. No. 023-055

Map Date

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER GRIFFIN (LAST) STEVEN (FIRST) A. (MIDDLE)

2) ADDRESS OF OWNER RT. 9 BOX 217E CHARLOTTE, NC ZIP 28208

3) PHONE NO Home 399-3948 Office —


4) LOCATION OF PROPERTY ~~OAKDALE~~ ACRES SIMPSON (STREET OR COUNTY ROAD) RD.

5) SUBDIVISION OAKDALE ACRES LOT NO 11 + 14 BLOCK NO E

MAP BOOK NO 8 PAGE NO 273

6) DEED REFERENCE DEED BOOK 2584 PAGE NO 401

Application is hereby made to the Mecklenburg County Department of Environmental Health for the purpose of [illegible] to determine the feasibility of [illegible] as required by the Mecklenburg County Sanitary Sewer Ordinance.



7) ACCURATELY DIAGRAM & DIMENSION LOT

OWNER Steven A. Griffin

HDES 76

Environmental Health Department's Copy

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE NORTH CAROLINA 28203

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

SIR.NO. 12415a 12489
T.C. NO. 033-075-02 & 033-075-18
MAP DATE
DATE February 21, 1979

NAME OF OWNER John I. Griffin and Steven A. Griffin

ADDRESS OF OWNER Route 9, Box 217 - F

LOCATION OF LOT Simpson Road, Lots 11 and 14

As determined under the Rules and Regulations promulgated by the Commission for Health Services, Division of Health Services, North Carolina Department of Human Resources, Raleigh, North Carolina, the soils on the lot described above were found to be unsuitable for the installation of an individual septic tank-soil absorption system. This site cannot be approved for a septic tank system due to the following reason:

Soil Structure Massive

Soil Permeability Unsuitable

Perched Water Table

Site Classification Unsuitable

Stephen D. Wood, Environmentalist

EHD 396
7/77

R